

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

**SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE**

CHP 343 (Rev. 12-17) OPI 062

NEW TERMINAL INFORMATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CA NUMBER 49302	FILE CODE NUMBER 17323	COUNTY CODE 33	BED
TERMINAL TYPE <input type="checkbox"/> Truck <input checked="" type="checkbox"/> Bus <input type="checkbox"/> Mod Limo	CODE S	OTHER PROGRAM(S)	LOCATION CODE 630	SUBAREA B15

CARRIER LEGAL NAME COACHELLA VALLEY USD	TERMINAL NAME (IF DIFFERENT)	TELEPHONE NUMBER (W/ AREA CODE) (760) 399-5127
--	------------------------------	---

TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE)

87225 CHURCH STREET THERMAL CA 92274

MAILING ADDRESS (NUMBER, STREET, CITY, ZIP CODE) (IF DIFFERENT FROM ABOVE)

PO BOX 847 THERMAL CA 92274

INSPECTION LOCATION (NUMBER, STREET, CITY OR COUNTY)

LICENSE, FLEET AND TERMINAL INFORMATION

HM LIC. NO.	HWT REG. NO.	IMS LIC. NO.	TRUCKS AND TYPES	TRAILERS AND TYPES	PASS VEH BY TYPE I 94 II	Mod Limo	DRIVERS 63	BIT FLEET SIZE Powered
EXP. DATE	EXP. DATE	EXP. DATE	REG. CT.	HW VEH.	HW CONT.	PPB/CSAT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		Towed
TERMINALS IDENTIFIED IN SECTION 34515(b) CVC <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			FILE CODE NUMBERS OF TERMINALS INCLUDED IN INSPECTION AS A RESULT OF SECTION 34515(b) CVC					

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) APOLONIO DEL TORE (POLO)	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE) (760) 835-7149
EMERGENCY CONTACT (NAME) SEAN ROBY	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE)

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL FOR LAST YEAR [2018]

A <input type="checkbox"/> UNDER 15,000	B <input type="checkbox"/> 15,001 - 50,000	C <input type="checkbox"/> 50,001 - 100,000	D <input type="checkbox"/> 100,001 - 500,000	E <input type="checkbox"/> 500,001 - 1,000,000	F <input checked="" type="checkbox"/> 1,000,001 - 2,000,000	G <input type="checkbox"/> 2,000,001 - 5,000,000	H <input type="checkbox"/> 5,000,001 - 10,000,000	I <input type="checkbox"/> MORE THAN 10,000,000
--	---	--	---	---	--	---	--	--

OPERATING AUTHORITIES OR PERMITS

PUC <input type="checkbox"/> T	<input type="checkbox"/> TCP <input type="checkbox"/> PSC	MOTOR CARRIER OF PROPERTY PERMIT ACTIVE <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	IMS FITNESS EVALUATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
USDOT 2808913	<input type="checkbox"/> MC <input type="checkbox"/> MX	<input type="checkbox"/> MC <input type="checkbox"/> MX	REASON FOR INSPECTION SCHOOL BUS CERTIFICATION

INSPECTION FINDINGS		INSPECTION RATINGS: S = Satisfactory U = Unsatisfactory C = Conditional UR = Unrated N/A = Not Applicable				
REQUIREMENTS	VIOL	MAINTENANCE PROGRAM	DRIVER RECORDS	REG. EQUIPMENT	HAZARDOUS MATERIALS	TERMINAL
MAINTENANCE PROGRAM		1 2 3 4	1 2 3 4	1 2 3 4	1 2 3 4	1 2 3 4
DRIVER RECORDS		No. 9 Time	No. Time	No. 9 Time	TIME	TOTAL TIME
DRIVER HOURS		HAZARDOUS MATERIALS <input checked="" type="checkbox"/> No H/M Transported <input type="checkbox"/> No H/M violations noted	CONTAINERS/TANKS No. Time	VEHICLES PLACED OUT-OF-SERVICE Vehicles		Units
BRAKES		REMARKS THE FOLLOWING SCHOOL BUSES WERE NOT CERTIFIED: BUSES WERE NOT CERTIFIED DUE TO DEFECTIVE CHILD SAFETY ALERT SYSTEMS #14, 20, 22, 54, 55, 107, 110, 124, 125				
LAMPS & SIGNALS						
CONNECTING DEVICES						
STEERING & SUSPENSION						
TIRES & WHEELS						
EQUIPMENT REQUIREMENTS						
CONTAINERS & TANKS						
HAZARDOUS MATERIALS						

INSPECTION TYPE <input type="checkbox"/> I <input type="checkbox"/> R <input checked="" type="checkbox"/> Non-BIT	CPSS <input type="checkbox"/> Yes <input type="checkbox"/> No	CHP 345 <input type="checkbox"/>	CHP 100D COL. <input type="checkbox"/>	INSPECTION DATE(S) 06/13/2019	TIME IN	TIME OUT
INSPECTED BY (NAME(S)) SPAUNHURST	ID NUMBER(S) A14627	SUSPENSE DATE <input type="checkbox"/> Auto <input checked="" type="checkbox"/> None				

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through _____), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at (858) 650-3655 within 5 business days of the rating.

CURRENT TERMINAL RATING	CARRIER REPRESENTATIVE'S SIGNATURE	DATE 06/13/2019
CARRIER REPRESENTATIVE'S PRINTED NAME APOLONIO DEL TORE (POLO)	TITLE DIRECTOR	DRIVER LICENSE NUMBER STATE



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000034
Inspection Date: 06/13/2019
Start: 7:00 AM PS **End:** 7:15 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
USDOT: 2808913 **Phone#:** (760)399-5127
MC/MX#: **Fax#:**
State#: 49302
Location: THERMAL **Milepost:** **Shipper:** N/A
Highway: CHURCH ST **Origin:** N/A **Bill of Lading:** N/A
County: RIVERSIDE **Destination:** N/A **Cargo:** N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1141204	14	4DRBJADR63A950992	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-20	C-30

VIOLATIONS

Section	Type	Unit	QOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance-396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294

HazMat: No HM transported **Placard:** **Cargo Tank:**

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 353281; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 353281 06/12/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst **Badge #:** A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000035
Inspection Date: 06/13/2019
Start: 6:00 AM PS End: 6:15 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State:

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, QOS, Citation #, Verify Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 406926; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294
3000/45 Maintenance record missing

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000036
Inspection Date: 06/13/2019
Start: 7:15 AM PS **End:** 7:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
USDOT: 2808913 **Phone#:** (760)399-5127
MC/MX#: **Fax#:**
State#: 49302
Location: THERMAL **Milepost:** **Shipper:** N/A
Highway: CHURCH ST **Origin:** N/A **Bill of Lading:** N/A
County: RIVERSIDE **Destination:** N/A **Cargo:** N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1265588	22	4DRBJADRX3A955564	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-20	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1232(A) CCR /001	S	1	N		N	General maintenance--396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294
1232(A) CCR /001	S	1	N		N	General maintenance--396.3 (a)(1): CHP 292 holer missing cover

HazMat: No HM transported **Placard:** **Cargo Tank:**

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 429627; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 428098 05/23/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: Badge #:
 S. Spauhurst A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000037
Inspection Date: 06/13/2019
Start: 6:45 AM PS End: 7:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State#: 49302
Location: THERMAL Milepost: Shipper: N/A
Highway: CHURCH ST Origin: N/A Bill of Lading: N/A
County: RIVERSIDE Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1265680	54	1T7YUA2781289126	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 1/2
Left	1 1/2	1 1/2
Chamber	C-30	C-30

VIOLATIONS

Section	Type	Unit	QOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--386.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 134132; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 132922 05/24/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000038
Inspection Date: 06/13/2019
Start: 6:30 AM PS End: 6:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State:
State#: 49302
Location: THERMAL Milepost: Shipper: N/A
Highway: CHURCH ST Origin: N/A Bill of Lading: N/A
County: RIVERSIDE Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1265686	55	1T7YU4A2981289127	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 1/2
Left	1 1/2	1 1/2
Chamber	C-30	C-30

VIOLATIONS

Section	Type	Unit	QOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	I	N		N	N	General maintenance--396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 123746; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 123142 05/31/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000039
Inspection Date: 06/13/2019
Start: 6:15 AM PS End: 6:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State#: 49302
Location: THERMAL Milepost: Shipper: N/A
Highway: CHURCH ST Origin: N/A Bill of Lading: N/A
County: RIVERSIDE Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265503	107	1HVBADR4YA929841	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-20	C-30

VIOLATIONS

Section	Type	Unit	QOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	I	N		N	N	General maintenance--396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 370093; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294
3000/45 369252 05/29/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000040
Inspection Date: 06/13/2019
Start: 7:30 AM PS **End:** 7:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
USDOT: 2808913 **Phone#:** (760)399-5127
MC/MX#: **Fax#:**
State#: 49302
Location: THERMAL **Milepost:** **Shipper:** N/A
Highway: CHURCH ST **Origin:** N/A **Bill of Lading:** N/A
County: RIVERSIDE **Destination:** N/A **Cargo:** N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265613	110	1HVBBAAN7YH308809	25500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-16	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Bus is very dirty inside
13CCR 1242(G) /001	S	1	N		N	N	Not equipped with two fully charged fire extinguishers. - 393.95A: Wheel chair bus is missing both fire extinguishers

HazMat: No HM transported **Placard:** **Cargo Tank:**

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 141335; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 24; Veh #1 Type: 13; WC Passenger Capacity: 3; Bus Type: 1 ; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 141335 04/08/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000041
Inspection Date: 06/13/2019
Start: 5:30 AM PS End: 5:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State#: 49302
Location: THERMAL Milepost: Shipper: N/A
Highway: CHURCH ST Origin: Bill of Lading: N/A
County: RIVERSIDE Destination: Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361101	124	1GB6G3AG4A1173720	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS

Section	Type	Unit	QOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Defective child safety alert system CVC28160 13CCR1294
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Rear emergency door has folded paper between door plunger and switch - take folded paper away buzzer stays on

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 208624; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294
3000/45 Maintenance record missing

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000042
Inspection Date: 06/13/2019
Start: 5:45 AM PS End: 6:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#:
State#: 49302
Location: THERMAL Milepost: Shipper: N/A
Highway: CHURCH ST Origin: N/A Bill of Lading: N/A
County: RIVERSIDE Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, QOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 213887; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: NO CERT

Notes: NOT CERTIFIED DEFECTIVE CHILD SAFETY ALERT CVC28160 13CCR1294 3000/45 212932 05/30/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X

