

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

**SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE**

CHP 343 (Rev. 12-17) OPI 062

NEW TERMINAL INFORMATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CA NUMBER 49302	FILE CODE NUMBER 17323	COUNTY CODE 33	BED
TERMINAL TYPE <input type="checkbox"/> Truck <input checked="" type="checkbox"/> Bus <input type="checkbox"/> Mod Limo	CODE S	OTHER PROGRAM(S)	LOCATION CODE 630	SUBAREA B15

CARRIER LEGAL NAME COACHELLA VALLEY UNIFIED SCHOOL	TERMINAL NAME (IF DIFFERENT) DISTRICT	TELEPHONE NUMBER (W/ AREA CODE) (760) 399-5127
TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE) 87225 CHURCH ST THERMAL CA 92274		
MAILING ADDRESS (NUMBER, STREET, CITY, ZIP CODE) (IF DIFFERENT FROM ABOVE) PO BOX 847 THERMAL CA 92274	INSPECTION LOCATION (NUMBER, STREET, CITY OR COUNTY)	

LICENSE, FLEET AND TERMINAL INFORMATION

HM LIC. NO.	HWT REG. NO.	IMS LIC. NO.	TRUCKS AND TYPES	TRAILERS AND TYPES	PASS VEH BY TYPE I 94 II Mod Limo	DRIVERS 63	BIT FLEET SIZE Powered
EXP. DATE	EXP. DATE	EXP. DATE	REG. CT.	HW VEH.	HW CONT.	PPB/CSAT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Towed
TERMINALS IDENTIFIED IN SECTION 34515(b) CVC <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			FILE CODE NUMBERS OF TERMINALS INCLUDED IN INSPECTION AS A RESULT OF SECTION 34515(b) CVC				

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) APOLONIO DEL TORE (POLO)	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE) (760) 835-7149
EMERGENCY CONTACT (NAME) RAMON AVALOS	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE) (760) 391-1116

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL FOR LAST YEAR [2017]

A <input type="checkbox"/> UNDER 15,000	B <input type="checkbox"/> 15,001 - 50,000	C <input type="checkbox"/> 50,001 - 100,000	D <input type="checkbox"/> 100,001 - 500,000	E <input type="checkbox"/> 500,001 - 1,000,000	F <input checked="" type="checkbox"/> 1,000,001 - 2,000,000	G <input type="checkbox"/> 2,000,001 - 5,000,000	H <input type="checkbox"/> 5,000,001 - 10,000,000	I <input type="checkbox"/> MORE THAN 10,000,000
--	---	--	---	---	--	---	--	--

OPERATING AUTHORITIES OR PERMITS

PUC <input type="checkbox"/> T	<input type="checkbox"/> TCP <input type="checkbox"/> PSC	MOTOR CARRIER OF PROPERTY PERMIT ACTIVE <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	IMS FITNESS EVALUATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
USDOT USDOT NUMBER 2808913	<input type="checkbox"/> MC <input type="checkbox"/> MX	<input type="checkbox"/> MC <input type="checkbox"/> MX	REASON FOR INSPECTION ANNUAL SCHOOL BUS TERMINAL INSPECTION

INSPECTION FINDINGS		INSPECTION RATINGS: S = Satisfactory U = Unsatisfactory C = Conditional UR = Unrated N/A = Not Applicable					
REQUIREMENTS	VIOL	MAINTENANCE PROGRAM	DRIVER RECORDS	REG. EQUIPMENT	HAZARDOUS MATERIALS	TERMINAL	
MAINTENANCE PROGRAM		1 U 2 C 3 S 4 S	1 N/A 2 N/A 3 S 4 S	1 U 2 C 3 S 4 S	1 N/A 2 N/A 3 N/A 4 N/A	1 U 2 C 3 S 4 S	
DRIVER RECORDS		No. 20 Time 6.0	No. 16 Time 1.5	No. 20 Time 12.0	TIME	TOTAL TIME 19.5	
DRIVER HOURS		HAZARDOUS MATERIALS <input checked="" type="checkbox"/> No H/M Transported <input type="checkbox"/> No H/M violations noted	CONTAINERS/TANKS No. Time	VEHICLES PLACED OUT-OF-SERVICE Vehicles	Units		
BRAKES	2	REMARKS SEE ATTACHED PAGES (PART B AND PART C) FOR INSPECTION FINDINGS.					
LAMPS & SIGNALS	2						
CONNECTING DEVICES							
STEERING & SUSPENSION							
TIRES & WHEELS	1						
EQUIPMENT REQUIREMENTS	30						
CONTAINERS & TANKS							
HAZARDOUS MATERIALS							

INSPECTION TYPE <input type="checkbox"/> I <input type="checkbox"/> R <input checked="" type="checkbox"/> Non-BIT	NON-BIT	CPSS <input type="checkbox"/> Yes <input type="checkbox"/> No	CHP 345	CHP 100D COL. 2,305	INSPECTION DATE(S) 07/10-12/2018	TIME IN 0500	TIME OUT 1130
INSPECTED BY (NAME(S)) SPAUNHURST				ID NUMBER(S) A14627	SUSPENSE DATE <input checked="" type="checkbox"/> Auto <input type="checkbox"/> None		

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through 26), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at (858) 650-3655 within 5 business days of the rating.

CURRENT TERMINAL RATING SATISFACTORY	CARRIER REPRESENTATIVE'S SIGNATURE <i>Apolonio Del Tore</i>	DATE 07/12/2018
CARRIER REPRESENTATIVE'S PRINTED NAME APOLONIO DEL TORE (POLO)	TITLE DIRECTOR	DRIVER LICENSE NUMBER STATE

California Highway Patrol



US DOT #
2808913

Legal: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
Operating (DBA): RIVERSIDE COUNTY SCHOOLS

2

MC/MX #: **State #:** 49302 **Federal Tax ID:** 33-0765218 (EIN)

Review Type: Non-ratable Review - Special Study

Scope: Terminal **Location of Review/Audit:** Company facility in the U. S. **Territory:** F

Operation Types Interstate Intrastate

Carrier: N/A Non-HM
Shipper: N/A N/A
Cargo Tank: N/A

Business: Corporation
Gross Revenue: for year ending:

Company Physical Address:

87225 CHURCH ST
THERMAL, CA 92274

Contact Name:

Phone numbers: (1) 760- 399-5127 (2) Fax

E-Mail Address:

Company Mailing Address:

PO BOX 847
THERMAL, CA 92274

Carrier Classification

State Government

Cargo Classification

Passengers

Equipment

	Owned	Term Leased	Trip Leased	Owned	Term Leased	Trip Leased
School Bus, 16+	94	0	0			

Power units used in the U.S.: 94

Percentage of time used in the U.S.: 100

Does carrier transport placardable quantities of HM? No

Is an HM Permit required? N/A

Driver Information

	Inter	Intra	Average trip leased drivers/month:
< 100 Miles:		63	0
>= 100 Miles:			Total Drivers: 63
			CDL Drivers: 63





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal
U.S. DOT #: 2808913 State #: 49302

3

Review Date:
07/12/2018

Part A

QUESTIONS regarding this report may be directed to the Border Division
Motor Carrier Safety Unit at

9330 Farnham Street
San Diego, CA 92123
(858) 650-3655

This TERMINAL REVIEW deals only with safety compliance at this terminal.

Person(s) Interviewed

Name: APOLONIO DEL TORO (POLO)

Title: DIRECTOR OF TRANSPORTATION

Name:

Title:





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal
U.S. DOT #: 2808913 State #: 49302

4

Review Date:
07/12/2018

Part B Violations

Safety Fitness Rating Information:

Total Miles Operated 1,000,000
Recordable Accidents 0

OOS Vehicle (CR): 0
Number of Vehicle Inspected (CR): 0
OOS Vehicle (MCMIS): 0
Number of Vehicles Inspected (MCMIS): 0

Your proposed safety rating is :

This Review is not Rated.





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal
U.S. DOT #: 2808913 State #: 49302

5

Review Date:
07/12/2018

Part B Requirements and/or Recommendations

1. Questions related to this inspection may be directed to the Border Division Motor Carrier Safety Unit at (858) 650-3655.





6

Part C

Reason for Review: Other SCHOOL BUS TERMINAL
Planned Action: Compliance Monitoring

Parts Reviewed Certification:

325 382 383 387 390 391 392 393 395 396 397 398 399 171 172 173 177 178 180

Prior Reviews **Prior Prosecutions** **Reason not Rated:** Special Study **Study Code:** CA
 7/27/2017
 2/3/2017
 10/12/2016

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle? Yes - Intrastate
 Does carrier transport placardable quantities of hazardous materials? Not Applicable
 Unsat/Unfit rule:

Corporate Contact: APOLONIO DEL TORO (POLO) **Special Study Information:**
Corporate Contact Title: DIRECTOR OF TRANSPORTATION

Remarks:

Terminal Name: Coachella Valley Unified School District CA# - 49302
 Terminal Address: 87225 Church St Thermal CA FCN # - 17323

RATING INFORMATION:
 In accordance with 13 CCR 1233, this terminal has been rated satisfactory.

There were no on-highway inspections available to use to fulfill the required vehicle inspection sample.

REFERENCES

The full text of the California Vehicle Code (CVC) is available online at leginfo.ca.gov/calaw, and the full text of Title 13, California Code of Regulations, (13CCR), is available online at ccr.oal.ca.gov. Links to these two sites can be found at chp.ca.gov.
 California Air Resources Board Hotline: (866) 634-3735

Upload Authorized:	Yes	No
Authorized by:		Date:
Uploaded:	Yes	No
Verified by:		Failure Code:
		Date:





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271457
Inspection Date: 07/11/2018
Start: 6:00 AM PS End: 6:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: Bill of Lading: N/A
Destination: Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2001	CA	1265526	02	1HVBADR91A912104	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Bus not swept
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Body damage paint does not match National School Bus Yellow black faded yellow showing through
1268(F)(4) CCR	S	1	N		N	N	Emergency door sign required--392.2: Door opening instructions incomplete "Push Out" missing on both doors left and right side

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 370656; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 02/16/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271448
Inspection Date: 07/10/2018
Start: 6:30 AM PS End: 7:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: Destination:
Bill of Lading: N/A
Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2001	CA	1265578	03	1HVBADR11A912114	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Body damaged paint does not match National School Bus Yellow
396.3A1	F	1	N		N	N	General maintenance--396.3 (a)(1): Seat repairs needed last seat on the right side
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Emergency door push up seat mounting bolt loose

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 343039; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 03/15/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



9



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271449
Inspection Date: 07/10/2018
Start: 7:00 AM PS End: 7:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Destination: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2002	CA	1265580	06	1HVBADR42A940104	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): 2 aerosol cans in dash storage compartment
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Low air warning device buzzer very weak and the light did not come on at first, light came on when inspection was completed
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): #3 left side seat back needs repair

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 348125; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 03/15/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271449

10



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271450
Inspection Date: 07/10/2018
Start: 7:30 AM PS End: 8:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#:
State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2002	CA	1238995	09	1HVBJADRX2A940107	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
396.3A1	F	1	N		N	N	General maintenance--396.3 (a)(1): Bus not swept
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): #4 left side window latch defective

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 367087; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 04/05/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271451
Inspection Date: 07/10/2018
Start: 8:30 AM PS End: 9:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Destination: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2002	CA	1265584	13	1HVBADR52A942959	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Paint on top, front and back peeling and does not match National School Bus Yellow
1278(C) CCR	S	1	N		N	N	Passenger seat cushion not secured to frame--392.2
396.3A1	F	1	N		N	N	General maintenance--396.3 (a)(1): Bus not swept

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 343356; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 04/17/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271452
Inspection Date: 07/10/2018
Start: 9:00 AM PS End: 9:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1265592	19	4DRBJADR13A950995	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1243(C) CCR	S	1	N		N	N	First aid kit incomplete--392.2: Missing 1 of 16 1x3 bandages
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): #13 right side seat needs repair
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Loose exhaust clamp muffler to tail pipe no leaks detected by hand
1232(A) CCR /005	S	1	N		N	N	Wheel/rim violation--393.205(a): Axle 2 left side inner wheel shader valve is not accesable

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 305838; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 04/17/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



14



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271454
Inspection Date: 07/10/2018
Start: 10:30 AM PS End: 11:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Destination: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2006	CA	1223249	38	1T7YU4F2961167633	37600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	C-30	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1232(A) CCR /001	S	1	N		N N	General maintenance--396.3 (a)(1): Left side emergency push up seat needs repair

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 139458; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 05/17/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



15



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271455
Inspection Date: 07/10/2018
Start: 11:00 AM PS End: 11:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWR	CVSA Existing	CVSA #
1	SB	CHEV	2004	CA	1265604	41	1GDJG31U341225978	12000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
396.3A1	F	1	N		N	N General maintenance--396.3 (a)(1): Bus not swept
24252(A) VC	S	1	N		N	N Required lamp(s) Inoperative--393.9(a): Headlight right side loose in mounting bracket

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 225987; Passenger Capacity: 24; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 05/17/2018

Rear disc brake pads showing excessive wear

Front right side tie rod end has up and down movement while under power, does not move by hand

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



16



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271458
Inspection Date: 07/11/2018
Start: 6:30 AM PS End: 7:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:

Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1265680	54	1T7YUA2781289126	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-30	C-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 108893; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 06/14/2018

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271456
Inspection Date: 07/10/2018
Start: 11:30 AM PS End: 12:00 PM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1262023	57	1T7YU4A2281289129	37600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	C-30	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): #5, 13, right side; #12 left side seat backs need repair
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Emergency window exit opening instructions are peeling off #9 window
24252(A) VC	S	1	N		N	N	Required lamp(s) inoperative--393.9(a): Right side low beam headlight

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 23477; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 05/18/2017

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271456



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271460
Inspection Date: 07/11/2018
Start: 7:30 AM PS End: 8:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265505	104	1HVBJADR4YA930195	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-20	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1278(C) CCR	S	1	N		N N	Passenger seat cushion not secured to frame-392.2

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 413884; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 04/17/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271460

19



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271459
Inspection Date: 07/11/2018
Start: 7:00 AM PS **End:** 7:30 AM PS
Inspection Level: V - Terminal
HM inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State:
State:

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265504	106	1HVBJADR8YA930197	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Left side emergency door seat back needs repair
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Front panel and body damage does not match National School Bus Yellow

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 379465; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Notes: Last certification 04/17/2018

Drag link ball end at steering arm moves up and down under power but not by hand

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271461
Inspection Date: 07/11/2018
Start: 8:30 AM PS End: 9:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost: Shipper: N/A
Origin:
Destination:
Bill of Lading: N/A
Cargo:

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, VerifyCrash, Violations Discovered

HazMat: No HM transported Placard: Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 342231; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271462
Inspection Date: 07/11/2018
Start: 9:00 AM PS End: 9:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2008	CA	1265681	113	1BAKB CPA38F248555	30280		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 1/2
Chamber	L-24*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1232(A) CCR /001	S	1	N		N	General maintenance--396.3 (a)(1): Bus not swept and front outside dirty
1232(A) CCR /001	S	1	N		N	General maintenance--396.3 (a)(1): Defective to seat foam #2 on the right side
26453 VC /011	S	1	N		N	Other brake violations--396.3A1B: Anti-lock brake sensor wire chafing steering are ball end nut on the left side of axle 1

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 224961; Passenger Capacity: 24; Veh #1 Type: 13; WC Passenger Capacity: 7; Bus Type: 1

Notes: Last certification 04/05/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271462

22



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271463
Inspection Date: 07/11/2018
Start: 9:30 AM PS End: 10:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2008	CA	1265695	114	1BAKBCPA08F248562	30280		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-24*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Paint faded and peeling on hood and does not match National School Bus Yellow
396.9D2	F	1	N		N	N	Failure to correct defects noted on previous inspection report: See report CAA146271344 dated 04/05/2018

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 110668; Passenger Capacity: 24; Veh #1 Type: 13; WC Passenger Capacity: 7; Bus Type: 1

Notes: Last certification 04/05/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



23



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271464
Inspection Date: 07/11/2018
Start: 10:00 AM PS End: 10:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361101	124	1GB6G3AG4A1173720	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 178642; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1

Notes: Last certification 06/14/2018

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271464

24



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271465
Inspection Date: 07/12/2018
Start: 5:30 AM PS End: 6:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: Bill of Lading: N/A
Destination: Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361086	125	1GB6G3AG5A117852	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported **Placard:** **Cargo Tank:**

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 189983; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1

Notes: Last certification 06/14/2018
Rear spring shackles worn on axle 2 both sides

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



25



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271466
Inspection Date: 07/12/2018
Start: 6:00 AM PS End: 6:30 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State:
State:

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361103	129	1GB6G3AG2A1173604	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 224960; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1

Notes: Last certification 04/17/2018

Rear spring shackles showing excessive wear on axle 2 both sides

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CAA146271466



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAA146271467
Inspection Date: 07/12/2018
Start: 6:30 AM PS End: 7:00 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: COACHELLA
Highway: AIRPORT BLVD
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2017	CA	1518667	134	1BABGBAA1JF334893	30280		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-24*	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 27115; Passenger Capacity: 40; Veh #1 Type: 13; WC Passenger Capacity: 4; Bus Type: 1

Notes: Last certification 03/15/2018

CNG fuel shut of stickers are in the wrong location - should be a couple of feet behind axle 1 opening

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

7/11/2018 3:03:48 PM



Basic Terminal Information for Term#: 17323
COACHELLA VALLEY UNIFIED SCHOOL DISTRICT, CA# 49302

Location 87225 CHURCH ST THERMAL, CA, US92274 (760)399-5127 CHP Area: 630 County Code: 33 Sub Area: B15	Mailing Address P O BOX 847 THERMAL, CA US 92274
--	---

Fleet Information
 Trucks: 1 Trailers: 1 Vehicles: 96 Bus 1: 94 Drivers: 63 BIT Fleet: 2
 Types Owned: N/A
 Types of Operation: SBUS

Terminal Emergency Contacts

APOLONIO DEL TORE (POLO)	Day: (760)399-5127	Night: (760)835-7149
RAMON AVALOS	Day: (760)399-5127	Night: (760)391-1116

Status ACTIVE as of 09/06/1988 Last 343 Update: 06/14/2018 Driver Records: Yes Vehicle Records: Yes	California Mileage		IMS License
	Year	Mileage	
	2017	1000001	
	2016	500001	

Inspection History

Inspection Date	Maint.	Driver	Equip	Hazmat	Term	CHP345 Issued	BIT-Inspection Conducted	Inspection Type	Suspense Date
7/27/2017	S	S	S	N/A	S	NO	Not Applicable	SBUS	7/27/2018
2/3/2017	C	N/A	C	N/A	C	NO	Not Applicable	SBUS	8/2/2017
10/13/2016	U	N/A	U	N/A	U	YES	Not Applicable	SBUS	2/10/2017
6/16/2016	U	N/A	U	N/A	U	YES	Not Applicable	SBUS	10/14/2016
6/13/2016	U	N/A	U	N/A	U	NO	Not Applicable	SBUS	10/11/2016
3/4/2016	U	S	U	N/A	U	NO	Not Applicable	SBUS	7/1/2016
2/27/2015	S	S	S	N/A	S	NO	Not Applicable	SBUS	2/1/2016
3/12/2014	S	S	S	N/A	S	NO	Not Applicable	SBUS	3/1/2015
12/20/2013	S	S	S	N/A	S	NO	Renewal	TRK	12/20/2019
5/29/2013	S	N/A	S	N/A	S	NO	Not Applicable	SBUS	5/1/2014
12/13/2012	C	N/A	S	N/A	C	NO	Not Applicable	SBUS	6/1/2013
8/22/2012	U	S	U	N/A	U	YES	Not Applicable	SBUS	10/1/2012
5/23/2012	U	S	U	N/A	U	YES	Not Applicable	SBUS	7/1/2012
3/29/2012	S	S	S	N/A	S	NO	Renewal	TRK	3/1/2014
2/24/2011	S	S	S	N/A	S	NO	Not Applicable	SBUS	2/1/2012
8/27/2010	C	S	S	N/A	C	NO	Not Applicable	SBUS	2/1/2011
7/21/2010	S	S	S	N/A	S	NO	Renewal	TRK	7/1/2012
5/18/2010	U	U	U	N/A	U	YES	Not Applicable	SBUS	7/1/2010
7/31/2009	S	S	S	N/A	S	NO	Not Applicable	SBUS	7/1/2010
2/5/2009	C	S	S	N/A	C	NO	Not Applicable	SBUS	8/1/2009
10/1/2008	U	U	U	N/A	U	YES	Not Applicable	SBUS	12/1/2008
7/22/2008	S	S	S	N/A	S	NO	Renewal	TRK	7/1/2010
10/11/2007	S	S	S	N/A	S	NO	Not Applicable	SBUS	10/1/2008