



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CAN7FT000038
Inspection Date: 06/12/2019
Start: 7:50 AM PT End: 8:50 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

FIRST STUDENT INC
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202
USDOT: 354406
MC/MX#: 191534
State#: 14019
Location: PALM SPRINGS
Highway:
County: RIVERSIDE

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Milepost: Shipper: N/A
Origin: Bill of Lading: N/A
Destination: Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWWR	CVSA Existing	CVSA #
1	SB	CHEV	2015	CA	7NNX210	152341	1GB3G3BG6F1232971	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: B17; Odometer: 75794; File Code Number: 14829; PUC: 916; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 17; WC Passenger Capacity: 0 ; Bus Type: 1; School Bus Cert: 06-12-2019

Notes: LAST CERT: 6-13-18 / 59679
LAST 45/3000 INSP: 6-10-19 / 75625

NOTE: NO OPERATIONAL BATTERY DISCONNECT INSTALLED ON THIS BUS
CSAS SYSTEM OPERATING PROPERLY

Report Prepared By: M. Roth
Badge #: A09641

Copy Received By:

X

X

