

**SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE**

CHP 343 (Rev. 12-17) OPI 062

NEW TERMINAL INFORMATION <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CA NUMBER 49302	FILE CODE NUMBER 17323	COUNTY CODE 33	BED
TERMINAL TYPE <input type="checkbox"/> Truck <input checked="" type="checkbox"/> Bus <input type="checkbox"/> Mod Limo	CODE S	OTHER PROGRAM(S)	LOCATION CODE 630	SUBAREA B15

CARRIER LEGAL NAME COACHELLA VALLEY USD	TERMINAL NAME (IF DIFFERENT)	TELEPHONE NUMBER (W/ AREA CODE) (760) 399-5127
--	------------------------------	---

TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE)
87225 CHURCH ST THERMAL CA 92274

MAILING ADDRESS (NUMBER, STREET, CITY, ZIP CODE) (IF DIFFERENT FROM ABOVE)
PO BOX 847 THERMAL CA 92274-0847

INSPECTION LOCATION (NUMBER, STREET, CITY OR COUNTY)

LICENSE, FLEET AND TERMINAL INFORMATION

HIM LIC. NO.	HWT REG. NO.	IMS LIC. NO.	TRUCKS AND TYPES	TRAILERS AND TYPES	PASS VEH. BY TYPE I 95 II	Mod Limo	DRIVERS 84	BIT FLEET SIZE
EXP. DATE	EXP. DATE	EXP. DATE	REG. CT	HW VEH.	HW CONT.	PPB/CSAT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		Powered Towed
TERMINALS IDENTIFIED IN SECTION 34515(b) CVC <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			FILE CODE NUMBERS OF TERMINALS INCLUDED IN INSPECTION AS A RESULT OF SECTION 34515(b) CVC					

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) APOLONIO DEL TORE (POLO)	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE) (760) 835-7149
EMERGENCY CONTACT (NAME) SEAN ROBY	DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127	NIGHT TELEPHONE NO. (W/ AREA CODE) (760) 600-6947

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL FOR LAST YEAR [2018]

A <input type="checkbox"/> UNDER 15,000	B <input type="checkbox"/> 15,001 - 50,000	C <input type="checkbox"/> 50,001 - 100,000	D <input type="checkbox"/> 100,001 - 500,000	E <input type="checkbox"/> 500,001 - 1,000,000	F <input checked="" type="checkbox"/> 1,000,001 - 2,000,000	G <input type="checkbox"/> 2,000,001 - 5,000,000	H <input type="checkbox"/> 5,000,001 - 10,000,000	I <input type="checkbox"/> MORE THAN 10,000,000
--	---	--	---	---	--	---	--	--

OPERATING AUTHORITIES OR PERMITS

PUC <input type="checkbox"/> T	<input type="checkbox"/> TCP <input type="checkbox"/> PSC	MOTOR CARRIER OF PROPERTY PERMIT ACTIVE <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	IMS FITNESS EVALUATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
USDOT 2808913	<input type="checkbox"/> MC <input type="checkbox"/> MX	<input type="checkbox"/> MC <input type="checkbox"/> MX	REASON FOR INSPECTION SCHOOL BUS TERMINAL

INSPECTION FINDINGS		INSPECTION RATINGS: S = Satisfactory U = Unsatisfactory C = Conditional UR = Unrated N/A = Not Applicable					
REQUIREMENTS	VIOL	MAINTENANCE PROGRAM	DRIVER RECORDS	REG EQUIPMENT	HAZARDOUS MATERIALS	TERMINAL	
MAINTENANCE PROGRAM	3	1 C 2 S 3 S 4 U	1 N/A 2 S 3 S 4 S	1 C 2 S 3 S 4 U	1 N/A 2 N/A 3 N/A 4 N/A	1 C 2 S 3 S 4 U	
DRIVER RECORDS	2	No. 20 Time 10.5	No. 13 Time 3.0	No. 20 Time 11.0	TIME	TOTAL TIME 24.5	
DRIVER HOURS		HAZARDOUS MATERIALS <input checked="" type="checkbox"/> No H/M Transported <input type="checkbox"/> No H/M violations noted	CONTAINERS/TANKS No. Time	VEHICLES PLACED OUT-OF-SERVICE Vehicles 6 Units			
BRAKES	2	REMARKS SEE ATTACHED PAGES (PART B AND PART C) FOR INSPECTION FINDINGS, ACTIONS NECESSARY TO GAIN COMPLIANCE, DIRECTIVES AND VEHICLES DELCARED OUT OF SERVICE.					
LAMPS & SIGNALS	1	THE FOLLOWING BUSES WERE INSPECTED: #04, 05, 11, 16, 17, 21, 27, 34, 35, 40, 42, 47, 48, 111, 115, 116, 121, 122, 126, 130					
CONNECTING DEVICES		THE FOLLOWING BUSES WERE PLACED OUT OF SERVICE SEE CHP407F/343A OF THIS REPORT: #27, 34, 42, 47, 48, 121					
STEERING & SUSPENSION	1	THIS IS THE FIRST UNSATISFACTORY RATING OF THIS INSPECTION CYCLE					
TIRES & WHEELS							
EQUIPMENT REQUIREMENTS	26						
CONTAINERS & TANKS							
HAZARDOUS MATERIALS							


INSPECTION TYPE <input type="checkbox"/> I <input type="checkbox"/> R <input checked="" type="checkbox"/> Non-BIT	CPSS <input type="checkbox"/> Yes <input type="checkbox"/> No	CHP 345 <input type="checkbox"/>	CHP 100D GOL 11	INSPECTION DATE(S) 06/25-28/2019	TIME IN 1630	TIME OUT 1800
INSPECTED BY (NAME(S)) SPAUNHURST	ID NUMBER(S) A14627	SUSPENSE DATE <input checked="" type="checkbox"/> Auto <input type="checkbox"/> None				

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through 29), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at (858) 650-3655 within 5 business days of the rating.

CURRENT TERMINAL RATING UNSATISFACTORY	CARRIER REPRESENTATIVE'S SIGNATURE <i>Mc A. A. L...</i>	DATE 06/28/2019
CARRIER REPRESENTATIVE'S PRINTED NAME ERIK/LEE Maria G. Gandera	TITLE ASSIST SUPERINTENDENT	

California Highway Patrol

	US DOT # 2808913	Legal: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT Operating (DBA): RIVERSIDE COUNTY SCHOOLS	2 of 29						
MC/MX #:		State #: 49302	Federal Tax ID: 33-0765218 (EIN)						
Review Type: Non-ratable Review - Special Study									
Scope: Terminal		Location of Review/Audit: Company facility in the U. S.							
Territory: F									
Operation Types									
	Interstate	Intrastate							
Carrier:	N/A	Non-HM	Business: Corporation Gross Revenue: for year ending:						
Shipper:	N/A	N/A							
Cargo Tank:	N/A								
Company Physical Address:									
87225 CHURCH ST THERMAL, CA 92274									
Contact Name:									
Phone numbers: (1) 760- 399-5127 (2) Fax									
E-Mail Address:									
Company Mailing Address:									
PO BOX 847 THERMAL, CA 92274									
Carrier Classification									
State Government									
Cargo Classification									
Passengers									
Equipment									
	Owned			Term Leased			Trip Leased		
School Bus, 16+	95	0	0	0	0	0	0	0	0
Power units used in the U.S.: 95									
Percentage of time used in the U.S.: 100									
Does carrier transport placardable quantities of HM? No									
Is an HM Permit required? N/A									
Driver Information									
	Inter		Intra		Average trip leased drivers/month: 0				
< 100 Miles:	84		84		Total Drivers: 84				
>= 100 Miles:					CDL Drivers: 84				





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal

U.S. DOT #: 2808913

State #: 49302

30629

Review Date:

06/28/2019

Part A

QUESTIONS regarding this report may be addressed to Border Division
Motor Carrier Safety Unit at:

9330 Farnam Street
San Diego, CA 92123
(858) 650-3655

This TERMINAL REVIEW deals only with safety compliance at this terminal.

Person(s) Interviewed

Name: ERIK LEE

Title: ASSISTANT SUPERINTENDENT

Name:

Title:





4 of 29

Part B Violations

1 STATE	Primary: 13CCR1212.5(a)(4) CFR Equivalent: 395.5(b)(2)	Discovered 2	Checked 390	Drivers/Vehicles In Violation	Checked 13
------------	---	-----------------	----------------	----------------------------------	---------------

Description

Carrier permits or requires intrastate drivers of passenger carrying commercial motor vehicles to drive after having been on duty 80 hours within eight consecutive days.

Example

Driver Albert Garcia on 06/04/2019 drove over 80 hours in 8 days from 1:30pm to 6:00pm for 4 hours and 30 minutes and on 06/05/2019 drove over 80 hours in 8 days from 3:45pm to 4:30pm from 45 minutes

2 STATE	Primary: 13CCR1213(a)(1) CFR Equivalent: 395.8(a)	Discovered 1	Checked 390	Drivers/Vehicles In Violation	Checked 13
------------	--	-----------------	----------------	----------------------------------	---------------

Description

Entries on drivers records of duty status (logs) do not conform to the prescribed method of documentation as specified in Section 1213 CCR.

Example

Driver Paula Perez on 06/01/2019 marked city as Thermal and marked state as terminal

3 STATE	Primary: 13CCR1232(a) CFR Equivalent: 396.3(a)(1)	Discovered 1	Checked 20	Drivers/Vehicles In Violation	Checked 20
------------	--	-----------------	---------------	----------------------------------	---------------

Description

Carrier does not have an adequate preventative maintenance program, 6 of 20 vehicles inspected were placed out of service for violations that should have been detected, documented and corrected in an adequate preventative maintenance program.

Example

THE FOLLOWING BUSES WERE PLACED OUT OF SERVICE:

1. #27 2003 INTL LIC#1238999 EXHAUST LEAK
2. #34 2004 INTL LIC#1265594 EXHAUST LEAK
3. #42 2004 GMC LIC#1225971 DEFECTIVE BRAKE
4. #47 2007 THMS LIC#1265614 EXHAUST LEAK
5. #48 2007 THMS LIC#1265609 DEFECTIVE STEERING
6. #121 2010 CHEV LIC#1361084 DEFECTIVE DRIVE SHAFT CARRIER BEARING

4 STATE	Primary: 13CCR1215(e) CFR Equivalent: 396.11(a)(2)	Discovered 1	Checked 600	Drivers/Vehicles In Violation	Checked 20
------------	--	-----------------	----------------	----------------------------------	---------------

Description

Drivers daily vehicle condition reports do not accurately indicate the condition of the vehicle(s).

Example

1. #47 06/21/2019 defective driver compartment latches - not recorded on DVIR (door held closed with duct tape)
2. #48 06/25/2019 defective steering - not recorded on DVIR (bus was driven with a defective steering system)
3. #14 06/06/2019 child check alert marked Not/Applicable on DVIR (child check alert was not operational)
4. #16 06/21/2019 child check alert marked Not/Applicable on DVIR (child check alert was not operational)
5. #17 06/06/2019 child check alert marked OK on DVIR (child check alert was not operational)
6. #34 06/25/2019 defective emergency door warning light - not recorded on DVIR
7. #35 06/25/2019 defective emergency door warning light - not recorded on DVIR
8. #40 06/21/2019 defective first aid kit box seal - not recorded on DVIR
9. #121 06/24/2019 loose emergency door handle - not recorded on DVIR
10. #125 06/12/2019 child check alert marked OK on DVIR (child check alert was not operational)





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal
 U.S. DOT #: 2808913

State #: 49302

5 of 29

Review Date:
06/28/2019

Part B Violations

5 STATE	Primary: 13CCR1232(b) CFR Equivalent: 396.17(a)	Discovered 1	Checked 20	Drivers/Vehicles In Violation 8	Checked 20
------------	--	-----------------	---------------	---------------------------------------	---------------

Description

The motor carrier fails to inspect buses subject to its control every 3,000 miles or 45 calendar days, whichever occurs first, or more often if necessary to ensure safe operation.

Example

1. #27 04/12/2019 to 06/17/2019 402540 - 397805 = 6 days over 45 and 1735 miles over 3000
2. #34 11/20/2018 to 02/07/2019 471059 - 462306 = 34 days over 45 and 5753 miles over 3000
3. #35 11/06/2018 bus placed out of service - mileage 381265 on 11/06/2018 mileage on 04/11/2019 384260 = 156 days over 45 and 2995 miles over 3000
4. #47 04/22/2019 to 05/20/2019 -195029 - 192021 = 8 miles over 3000
5. #121 02/08/2019 to 04/10/2029 - 230547 -227276 = 4 days over 45 and 271 miles over 3000
6. #122 04/11/2019 to 06/24/2019 - 219352 - 214004 = 26 days over 45 and 2348 miles over 3000
7. #126 02/28/2019 to 05/03/2019 - 228015 - 224041 = 19 days over 45 and 974 miles over 3000
8. #130 04/23/2019 to 06/20/2019 - 249820 - 245691 = 13 days over 45 and 1129 miles over 3000

Safety Fitness Rating Information:		OOS Vehicle (CR): 0	
Total Miles Operated	1,000,000	Number of Vehicle Inspected (CR): 0	
Recordable Accidents	0	OOS Vehicle (MCMIS): 0	
		Number of Vehicles Inspected (MCMIS): 0	

Your proposed safety rating is :

This Review is not Rated.





bdf 29

Part B Requirements and/or Recommendations

1. Ensure that all drivers' records of duty status (logs) are accurate.
2. Ensure that all school bus driver transporting passengers in intrastate commerce comply with the hours of service limitations established in 13 CCR 1212.5(a). Do not allow drivers to exceed the 10, 16, and 80 hour limits.
3. Ensure drivers prepare and submit written daily vehicle inspections that accurately report defects present on each vehicle operated. A negative report shall indicate that no such conditions are present.
4. Require drivers perform adequate daily vehicle inspection to ensure safe and proper vehicle operation.
5. Implement more thorough and/or frequent safety inspections to ensure vehicles are kept in safe and proper operating condition.
6. Ensure vehicle Out-of-Service conditions are properly repaired before being returned to highway service.
7. Do not allow the operation of vehicles that are not in safe operating condition or not equipped and maintained as required by law.
8. Ensure school bus periodic preventive maintenance inspections are conducted as often as necessary to ensure safe operation. In no event are inspection intervals to exceed 3,000 miles or 45 calendar days, whichever occurs first.
9. To request a review of an unsatisfactory safety compliance rating you may contact the Border Division Motor Carrier Safety Unit Supervisor at (858) 650-3655 within five calendar days.
10. Questions related to this inspection may be directed to the Border Division Motor Carrier Safety Unit at (858) 650-3655.





RIVERSIDE COUNTY SCHOOLS (COACHELLA, VALLEY UNIFIED dba) - Terminal
 U.S. DOT #: 2808913 State #: 49302

7 of 29

Review Date:
06/28/2019

Part C

Reason for Review: Other SCHOOL BUS TERMINAL
 Planned Action: Compliance Monitoring

Parts Reviewed Certification:

325 382 383 387 390 391 392 393 395 396 397 398 399 171 172 173 177 178 180

Prior Reviews Prior Prosecutions Reason not Rated: Special Study Study Code: CA
 7/12/2018
 7/12/2018
 7/27/2017

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle? Yes - Intrastate
 Does carrier transport placardable quantities of hazardous materials? Not Applicable
 Unsat/Unfit rule: Not Applicable

Corporate Contact: ERIK LEE Special Study Information:
 Corporate Contact Title: ASSISTANT SUPERINTENDENT

Remarks:

Terminal Name: Coachella Valley Unified School District CA# - 49302
 Terminal Address: 87225 Church St Thermal CA FCN# - 17323

RATING INFORMATION:

In accordance with 13 CCR 1233, this terminal has been rated UNSATISFACTORY for the following reasons:

More than 20% of vehicles in the inspection sample were placed out of service. Violations generally spread over all inspected vehicles and/or maintenance records which, by their nature, should have been detected, documented and corrected under an acceptable inspection/maintenance program.

There were no on-highway inspections available to fulfill the required vehicle inspection sample.

Out-of-Service Vehicles:

13 CCR 1230(a) - The vehicles listed below have been placed Out-of-Service during this terminal inspection. These vehicles may be returned to highway service only after proper repair of the out-of-service condition(s).

1. #27 2003 INTL LIC#1238999 EXHAUST LEAK
2. #34 2004 INTL LIC#1265594 EXHAUST LEAK
3. #42 2004 GMC LIC#1225971 DEFECTIVE BRAKE
4. #47 2007 THMS LIC#1265614 EXHAUST LEAK
5. #48 2007 THMS LIC#1265609 DEFECTIVE STEERING
6. #121 2010 CHEV LIC#1361084 DEFECTIVE DRIVE SHAFT CARRIER BEARING

See part B for maintenance program and driver records violations.





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal

U.S. DOT #: 2808913

State #: 49302

8 of 29

Review Date:

06/28/2019

Part C

DIRECTION:

Carrier is directed to ensure drivers prepare and submit written daily vehicle inspections that accurately report defects present on each vehicle operated.

Carrier is directed to implement a more thorough 3000/45 and more frequent interval inspection program to ensure vehicles are in a safe and proper operating condition.

Carrier is directed to ensure that all vehicles that are not in safe operating condition are not used on the highway for any purpose as required by law.

Carrier is directed to correct all defects found on the vehicles during this inspection.

Carrier is directed that it is unlawful to operate the vehicles placed out of service on the highway for any purpose; this includes all vehicles with defective or inoperable child check safety alert systems.

CONSEQUENCES:

A reinspection will be conducted within 120 days of this inspection. The California Highway Patrol will attempt to contact your company within the 120 day period to schedule the reinspection. It is the motor carrier's responsibility, however, to ensure that the vehicles and all required records are made available for the reinspection, and the reinspection is conducted within the allotted time frame. Failure to correct the noted deficiencies and to upgrade compliance to satisfactory before the reinspection may result in any action deemed necessary to gain compliance by the California Highway Patrol.

REFERENCES

The full text of the California Vehicle Code (CVC) is available online at leginfo.ca.gov/calaw, and the full text of Title 13, California Code of Regulations, (13CCR), is available online at ccr.oal.ca.gov. Links to these two sites can be found at chp.ca.gov.

Upload Authorized:	Yes	No
Authorized by:		Date:
Uploaded:	Yes	No
		Failure Code:
Verified by:		Date:



INSPECTION DATE
06/28/2019

TERMINAL NAME COACHELLA VALLEY UNIFIED SCHOOL DISTRICT	CARRIER NAME (IF DIFFERENT)
ADDRESS 87225 CHURCH ST THERMAL CA 92274	PRINCIPAL (OWNERSHIP)

The motor carrier terminal named above was inspected this date and has been rated **UNSATISFACTORY**. This is the 1st unsatisfactory rating. As indicated on the accompanying Carrier Inspection/Safety Compliance Report, the principal areas of noncompliance are: (*Carrier is to initial spaces beside each box checked.*)

- m66 Maintenance Program/Records m66 Pull-Notice Program Hazardous Materials
 Driver Records/Hours of Service Vehicles/Tanks/Containers Drug & Alcohol Test Program

You are advised that:

- m66 Failure to correct the noted deficiencies and to upgrade compliance to satisfactory before the next inspection (see below) may result in action number(s) 4, 6 below by this Department.
- As a result of the inspection findings indicated above, this Department will initiate action number(s) _____ below without further notice. You may, within 5 business days of this notice, request a review of the inspection findings and the action(s) to be taken. To request a prompt and impartial review by the Division Special Services Commander, contact _____ Division at _____.
1. A recommendation to the Department of Motor Vehicles (DMV) to suspend or revoke your motor carrier of property permit _____ or private carrier of passengers certificate _____; Public Utilities Commission (PUC) to deny, suspend, or revoke your operating authority _____; Department of Consumer Affairs (DCA) to suspend, or revoke your operating authority _____; Carrier is placed on notice that the DMV/PUC/DCA will deny or suspend its permit, operating authority, or private carrier of passengers certificate on receipt of a written recommendation from the CHP, without further notice to the carrier. The DMV/PUC/DCA may thereafter revoke the carrier's permit, operating authority, or private carrier of passengers certificate.
2. A recommendation to the Department of Toxic Substances Control for administrative action, to include possible suspension, denial, revocation or assessment of significant monetary penalties regarding Hazardous Waste Transporter Registration, Number _____
3. Suspension or revocation of your Hazardous Materials Transportation License, Number _____; Inspection and Maintenance Station License, Number _____; or School Bus Contractor License, Number _____.
- m66 4. A complaint being filed with the District Attorney's office for prosecution. (A criminal or civil action may follow.)
5. A recommendation to the Federal Motor Carrier Safety Administration for administrative action against your United States Department of Transportation registration.
- m66 6. Other: Any action deemed necessary to gain compliance by the California Highway Patrol
- m66 A reinspection is required in 120 days(s) tentatively scheduled in 120 day(s).
- After a recommendation has been forwarded to the DMV/PUC/DCA, no reinspection will be conducted for the purpose of operating authority or permit reinstatement until requested by the DMV/PUC/DCA.

If you desire further information concerning this notice, you may telephone the Border Division Motor Carrier Safety Unit at (858) 650-3655.

I acknowledge receipt and understanding of the above notice.

SIGNATURE <u>Maria B. Lander</u>	TITLE ASSISTANT SUPERINTENDENT	
NAME (PRINTED) ERIK LEE / MARIA B LANDERA	STATE CA	DATE 06/28/2019
ISSUED BY SPAUNHURST	I.D. NUMBER A14627	



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000053
Inspection Date: 06/25/2019
Start: 8:30 AM PS End: 8:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2001	CA	1238997	04	1HVBJADRX1A912127	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
396.3A1	F	1	N		N N	General maintenance--396.3 (a)(1): Loose object on dash and behind driver seat, graffiti on back of seat by the emergency door on the left side and bus has not been swept

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 419941; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 01/17/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000054
Inspection Date: 06/25/2019
Start: 7:00 AM PS End: 7:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/IX#: _____
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: _____ State: _____
Date of Birth: _____
CoDriver:
License#: _____ State: _____
Date of Birth: _____
Milepost: _____ Shipper: N/A
Origin: _____
Destination: _____

Bill of Lading: N/A
Cargo: _____

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2001	CA	1265579	05	1HVBJADR11A912128	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
396.3A1	F	1	N		N	N	General maintenance--396.3 (a)(1): Several seats need repairs and the bus has not been swept

HazMat: No HM transported

Placard: _____

Cargo Tank: _____

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 375170; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 01/17/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By: _____

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000055
Inspection Date: 06/25/2019
Start: 7:30 AM PS End: 7:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2002	CA	1265582	11	1HVBJADR32A940109	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 359858; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 03/14/2019

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



13 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000056
Inspection Date: 06/25/2019
Start: 9:00 AM PS End: 9:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2001	CA	1265587	16	1HVBRAAN11A936861	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1256.5(A)(1) CCR	S	1	N		N	N	School bus color not authorized--392.2: Paint on hood has deteriorated and does not match National School Bus Yellow
24004 VC	S	1	N		N	N	Failure to correct defects noted on previous inspection report--396.9D2: Violation on report number CAA146271502 not repaired - 1256.5(A)(1) Paint on hood deteriorated
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Center carrier bearing is loose in mounting bracket has less than 1/2 inch up and down movement
24004 VC	S	1	N		N	N	Failure to correct defects noted on previous inspection report--396.9D2: Violation on report number CAA146271502 not repaired - 1232(A) carrier bearing loose in mounting bracket
392.2	F	1	N		N	N	Violation of Local Laws - Explain: 13CCR 1294(a) All school buses shall be equipped with a child safety alert system meeting the requirements of this section

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 245530; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 36; Veh #1 Type: 13; WC Passenger Capacity: 1; Bus Type: 1; School Bus Cert: TERMINAL

Notes: Axle 1 both tie rod ends have up and down movement under power

It is unlawful to use the vehicle described herein for transportation of school pupils until the defects noted have been corrected Authority 13CCR 1230

LAST CERTIFICATION 09/13/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000057
Inspection Date: 06/25/2019
Start: 9:30 AM PS End: 9:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1162408	17	4DRBRAAN33B951831	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1278(C) CCR	S	1	N		N	N	Passenger seat cushion not secured to frame--392.2: Several seat cushions not secure to seat frame
392.2	F	1	N		N	N	Violation of Local Laws - Explain:: 13CCR 1294(a) All school buses shall be equipped with a child safety alert system meeting the requirements of this section

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 18477; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 36; Veh #1 Type: 13; WC Passenger Capacity: 1; Bus Type: 1; School Bus Cert: TERMINAL

Notes: Axle 2 transverse stabilizer rod has worn bushings

It is unlawful to use the vehicle described herein for transportation of school pupils until the defects noted have been corrected Authority 13CCR 1230

LAST CERTIFICATION 05/17/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



15 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000058
Inspection Date: 06/25/2019
Start: 10:00 AM PS End: 10:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

State:
State:
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 409356; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: Paint is peeling

LAST CERTIFICATION 07/25/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000059
Inspection Date: 06/25/2019
Start: 10:30 AM PS End: 10:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1238999	27	4DRBJADR53A957478	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1261(G) CCR	S	1	Y		U	N	Exhaust leaks at system repairs--393.83 (g); Exhaust leak at turbo to muffler tube clamp - can feel leak by hand when engine is at idle

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 402869; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
LAST CERTIFICATION 12/20/2018

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



17 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000061
Inspection Date: 06/26/2019
Start: 8:00 AM PS End: 8:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, VerifyCrash, Violations Discovered

HazMat: No HM transported
Placard:
Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 490575; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
LAST CERTIFICATION 08/23/2018

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



18 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000062
Inspection Date: 06/26/2019
Start: 7:30 AM PS End: 7:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2004	CA	1265602	35	4DRBJADR84A958738	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Seats are in need of repairing
1268(F)(3) CCR	S	1	N		N	N	Emergency exit warning device missing or defective--392.2: Warning light on dash defective warning buzzer does operate

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 396064; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 09/13/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB000062

19 of 27



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000063
Inspection Date: 06/26/2019
Start: 7:00 AM PS End: 7:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COAGHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913 Phone#: (760)399-5127
MC/MX#: Fax#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: Bill of Lading: N/A
Destination: Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2014	CA	1418766	40	1BDBNBAA6EF300673	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-24*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1243(B) CCR /001	S	1	N		N	N	First aid kit not sealed against entry of dust or moisture, maintained--392.2: First aid kit container has defective closure tabs
392.2	F	1	N		N	N	Violation of Local Laws - Explain:: 13CCR 1294(a) All school buses shall be equipped with a child safety alert system meeting the requirements of this section

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 125317; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: CNG; Passenger Capacity: 78; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to use the vehicle described herein for transportation of school pupils until the defects noted have been corrected Authority 13CCR 1230
LAST CERTIFICATION 07/25/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



20 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000064
Inspection Date: 06/26/2019
Start: 11:00 AM PS End: 11:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, VerifyCrash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 24; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: See report CAA146271506 09/13/2018 in notes Axle 1 left side has a worn outer disc brake pad very close to brake indicator mark

It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
LAST CERTIFICATION 09/13/2018

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
Badge #: A14627

Copy Received By:

X

X



21 of 29



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000065
 Inspection Date: 06/26/2019
 Start: 9:30 AM PS End: 9:50 AM PS
 Inspection Level: V - Terminal
 HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
 USDOT: 2808913
 MC/MX#: _____
 State#: 49302
 Location: THERMAL
 Highway: CHURCH ST
 County: RIVERSIDE

Phone#: (760)399-5127
 Fax#: _____

Driver: _____ State: _____
 License#: _____
 Date of Birth: _____
 CoDriver: _____
 License#: _____ State: _____
 Date of Birth: _____
 Milepost: _____ Shipper: N/A
 Origin: N/A Bill of Lading: N/A
 Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2007	CA	1265614	47	4UZABPCS27CW47895	25500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Loose trash can and objects on the dash Upper compartment door is held close with tape Entrance door upper seal is held in place with tape
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Several seats are in need of repair
1261(G) CCR	S	1	Y		U	N	Exhaust leaks at system repairs--393.83 (g): Exhaust leak at turbo pipe to flex pipe before the particulate trap can feel leak by hand at engine idle

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 197970; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 4; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
 LAST CERTIFICATION 01/17/2019

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
 Badge #: A14627

Copy Received By:

X

X



22 of 29



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000066
 Inspection Date: 06/26/2019
 Start: 9:00 AM PS End: 9:20 AM PS
 Inspection Level: V - Terminal
 HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
 USDOT: 2808913
 MC/MX#: _____
 State#: 49302
 Location: THERMAL
 Highway: CHURCH ST
 County: RIVERSIDE

Driver:
 License#: _____ State: _____
 Date of Birth: _____
 CoDriver:
 License#: _____ State: _____
 Date of Birth: _____
 Milepost: _____ Shipper: N/A
 Origin: N/A
 Destination: N/A

Bill of Lading: N/A
 Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2007	CA	1265609	48	4UZABPCS07CW47894	25500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /014	S	1	Y		U	N	Steering lash OOS violation-393.209(b): Power steering wheel measured 18 inches Steering lash exceeded 45 degrees and measured more than 7 1/8 inch travel before steering axle tires moved

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 241287; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 30; Veh #1 Type: 13; WC Passenger Capacity: 4; Bus Type: 1; School Bus-Cert: TERMINAL

Notes: MCS-I requested bus for inspection, carrier explained that it was on a summer school route MCS-I request bus upon return. Carrier place bus out of service upon return because the driver said that the steering lash was excessive upon pre-trip and used the bus in transporting school pupils
 It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
 LAST CERTIFICATION 01/17/2019

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
 Badge #: A14627

Copy Received By:

X

X



23 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000067
Inspection Date: 06/26/2019
Start: 9:00 AM PS End: 9:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:

Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2008	CA	1265684	111	1BAKBCPAX8F248553	30280		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-24*	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 159269; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 24; Veh #1 Type: 13; WC Passenger Capacity: 7; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 03/14/2019

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB000067

24 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000068
Inspection Date: 06/26/2019
Start: 10:00 AM PS End: 10:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWR	CVSA Existing	CVSA #
1	SB	BLUB	2008	CA	1258024	115	1BAKBCPA28F248563	30280		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-24*	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance-396.3 (a)(1): Center carrier bearing is loose in bracket less than 1/2 inch up and down movement hand pressure
26453 VC /011	S	1	N		N	N	Other brake violations-396.3A1B: Emergency stop system defective when draining primary tank the secondary tank drains with it

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 24; Veh #1 Type: 13; WC Passenger Capacity: 7; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 03/14/2019

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



25 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000060
Inspection Date: 06/26/2019
Start: 10:30 AM PS End: 10:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

State:
State:
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 83116; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 84; Veh #1 Type: 13; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 08/23/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



26 of 29



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000069
Inspection Date: 06/25/2019
Start: 11:00 AM PS **End:** 11:20 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT		Driver:	
83800 AIRPORT BLVD		License#:	State:
THERMAL, CA, 92274		Date of Birth:	
USDOT: 2808913	Phone#: (760)399-5127	CoDriver:	
MC/MX#:	Fax#:	License#:	State:
State#: 49302		Date of Birth:	
Location: THERMAL	Milepost:	Shipper: N/A	
Highway: CHURCH ST	Origin: N/A	Bill of Lading: N/A	
County: RIVERSIDE	Destination: N/A	Cargo: N/A	

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361084	121	1GB6G3AG5A1173824	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	General maintenance--396.3 (a)(1): Rear emergency door operating handle is loose.
1232(A) CCR /001	S	1	Y		U	N	General maintenance--396.3 (a)(1): Center carrier bearing is defective and has more than 1/2 inch up and down movement by hand pressure

HazMat: No HM transported **Placard:** **Cargo Tank:**

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 238062; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to operate the vehicle described here in on the highway for any purpose Authority 13CCR 1230
 LAST CERTIFICATION 08/23/2018

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst **Badge #:** A14627

Copy Received By:

X _____ X _____



27 of 29



California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 650-3600
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000070
 Inspection Date: 06/25/2019
 Start: 8:00 AM PS End: 8:20 AM PS
 Inspection Level: V - Terminal
 HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
 83800 AIRPORT BLVD
 THERMAL, CA, 92274
 USDOT: 2808913
 MC/MX#: _____
 State#: 49302
 Location: THERMAL
 Highway: CHURCH ST
 County: RIVERSIDE

Phone#: (760)399-5127
 Fax#: _____

Driver:
 License#: _____ State:
 Date of Birth: _____
 CoDriver:
 License#: _____ State:
 Date of Birth: _____
 Milepost: _____ Shipper: N/A
 Origin: N/A Bill of Lading: N/A
 Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361102	122	1GB6G3AG3A1173823	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 219352; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 08/23/2018

Report Prepared By: Badge #:
 S. Spaunhurst A14627

Copy Received By:

X

X



02808913 CA CANBAB000070



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000071
Inspection Date: 06/25/2019
Start: 11:30 AM PS End: 11:50 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#: State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Phone#: (760)399-5127
Fax#:

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:

Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2010	CA	1361087	126	1GB6G3AG0A1173360	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: TERMINAL

Notes: LAST CERTIFICATION 08/23/2018

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X



29 of 29



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 650-3600
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB000072
Inspection Date: 06/25/2019
Start: 12:00 PM PS End: 12:20 PM PS
Inspection Level: V - Terminal
HM Inspection Type: None

COACHELLA VALLEY UNIFIED SCHOOL DISTRICT
83800 AIRPORT BLVD
THERMAL, CA, 92274
USDOT: 2808913
MC/MX#:
State#: 49302
Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost:
Origin:
Destination:
Shipper: N/A

State:
State:
Bill of Lading: N/A
Cargo:

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, QOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Beat/Sub Area: 630; Odometer: 249930; File Code Number: 17323; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: G; Passenger Capacity: 20; Veh #1 Type: 13; WC Passenger Capacity: 8; Bus Type: 1; School Bus Cert: TERMINAL

Notes: It is unlawful to use the vehicle described herein for transportation of school pupils until the defects noted have been corrected Authority 13CCR 1230
LAST CERTIFICATION 07/25/2018

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst
Badge #: A14627

Copy Received By:

X

X

