

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL
SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE
CHP 343 (Rev. 12-17) OPI 062

NEW TERMINAL INFORMATION
CA NUMBER 49302
FILE CODE NUMBER 17323
COUNTY CODE 33
TERMINAL TYPE
OTHER PROGRAM(S)
LOCATION CODE 630
SUBAREA B15

CARRIER LEGAL NAME COACHELLA VALLEY USD
TERMINAL NAME (IF DIFFERENT)
TELEPHONE NUMBER (W/ AREA CODE) (760) 399-5127

TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE)
87225 CHURCH STREET THERMAL CA 92274

MAILING ADDRESS (NUMBER, STREET, CITY, ZIP CODE) (IF DIFFERENT FROM ABOVE)
PO BOX 847 THERMAL CA 92274
INSPECTION LOCATION (NUMBER, STREET, CITY OR COUNTY)
SAME

LICENSE, FLEET AND TERMINAL INFORMATION

HM LIC. NO. HWT REG. NO. IMS LIC. NO. TRUCKS AND TYPES TRAILERS AND TYPES PASS VEH BY TYPE
I 95 II Mod Limo
DRIVERS 84
BIT FLEET SIZE Powered
EXP. DATE EXP. DATE EXP. DATE REG. CT. HW VEH. HW CONT. PPB/CSAT
Yes No N/A Towed

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) EDWARD TORRES
DAY TELEPHONE NO. (W/ AREA CODE) (760) 399-5127
NIGHT TELEPHONE NO. (W/ AREA CODE)

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL FOR LAST YEAR [ 2022 ]

A UNDER 15,000 B 15,001 - 50,000 C 50,001 - 100,000 D 100,001 - 500,000 E 500,001 - 1,000,000 F 1,000,001 - 2,000,000 G 2,000,001 - 5,000,000 H 5,000,001 - 10,000,000 I MORE THAN 10,000,000

OPERATING AUTHORITIES OR PERMITS

PUC T TCP PSC
MOTOR CARRIER OF PROPERTY PERMIT ACTIVE
USDOT 2808913 MC MX
REASON FOR INSPECTION SCHOOL BUS TERMINAL

Table with columns: INSPECTION FINDINGS, REQUIREMENTS, VIOL, MAINTENANCE PROGRAM, DRIVER RECORDS, REG. EQUIPMENT, HAZARDOUS MATERIALS, TERMINAL. Includes inspection ratings and remarks.

SEE ATTACHED PAGES (PART B AND PART C) FOR INSPECTION FINDINGS.


INSPECTION TYPE NON-BIT CPSS CHP 345 CHP 100D COL.
INSPECTION DATE(S) 03/07-08 & 10/2023
TIME IN 0600 TIME OUT 1100
INSPECTED BY (NAME(S)) SPAUNHURST
ID NUMBER(S) A14627
SUSPENSE DATE Auto None

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through 26), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at (858) 650-3655 within 5 business days of the rating.

CURRENT TERMINAL RATING SATISFACTORY
CARRIER REPRESENTATIVE'S SIGNATURE
DATE 03/10/2023
CARRIER REPRESENTATIVE'S PRINTED NAME EDWARD TORRES
TITLE SUPERVISOR
DRIVER LICENSE NUMBER STATE

**California Highway Patrol**

	<b>US DOT #</b> 2808913	<b>Legal:</b> COACHELLA VALLEY UNIFIED SCHOOL DISTRICT <b>Operating (DBA):</b> RIVERSIDE COUNTY SCHOOLS	2 of 26			
<b>MC/MX #:</b> <b>State #:</b> 49302 <span style="background-color: black; color: black;">XXXXXXXXXX</span>		<b>Review Type:</b> Non-ratable Review - Special Study				
<b>Scope:</b> Terminal		<b>Location of Review/Audit:</b> Company facility in the U. S. <b>Territory:</b> F				
<b>Operation Types</b> <b>Interstate</b> <b>Intrastate</b>						
<b>Carrier:</b> N/A                      Non-HM		<b>Business:</b> Corporation				
<b>Shipper:</b> N/A                      N/A		<b>Gross Revenue:</b> <b>for year ending:</b>				
<b>Cargo Tank:</b> N/A						
<b>Company Physical Address:</b>						
87050 57TH AVE THERMAL, CA 92274						
<b>Contact Name:</b>						
<b>Phone numbers:</b> (1) 760- 399-5127                      (2)		<b>Fax</b>				
<b>E-Mail Address:</b>						
<b>Company Mailing Address:</b>						
PO BOX 847 THERMAL, CA 92274						
<b>Carrier Classification</b>						
State Government						
<b>Cargo Classification</b>						
Passengers						
<b>Equipment</b>						
	<b>Owned    Term Leased    Trip Leased</b>			<b>Owned    Term Leased    Trip Leased</b>		
School Bus, 16+	97	0	0			
Power units used in the U.S.: 97 Percentage of time used in the U.S.: 100						
<b>Does carrier transport placardable quantities of HM?</b> No						
<b>Is an HM Permit required?</b> N/A						
<b>Driver Information</b>						
	<b>Inter</b>	<b>Intra</b>	<b>Average trip leased drivers/month:</b> 0			
<b>&lt; 100 Miles:</b>		84	<b>Total Drivers:</b> 84			
<b>&gt;= 100 Miles:</b>			<b>CDL Drivers:</b> 84			





**RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal**  
U.S. DOT #: 2808913

State #: 49302

3 of 26

Review Date:  
03/10/2023

**Part A**

QUESTIONS regarding this report or the Border Division Motor Carrier  
Safety Unit

9330 Farnham Street  
San Diego, CA 92123  
(858) 944-6345

**This TERMINAL REVIEW deals only with safety compliance at this terminal.**

**Person(s) Interviewed**

**Name:** EDWARD TORRES

**Title:** SUPERVISOR

**Name:**

**Title:**





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal

U.S. DOT #: 2808913

State #: 49302

4 of 26

Review Date:

03/10/2023

Part B Violations

1 STATE	Primary: 13CCR1215(e) CFR Equivalent: 396.11(b)	Discovered 1	Checked 20	Drivers/Vehicles In Violation 2	Checked 20
------------	--	-----------------	---------------	---------------------------------------	---------------

Description

Drivers daily vehicle condition reports do not accurately indicate the condition of the vehicle(s).

Example

Drivers daily vehicle condition reports do not accurately indicate the condition of the vehicle(s).

2021 BLUB LIC# 1603238 See CHP407F for violation. Defect was not recorded on the current DVIR.

2020 BLUB LIC# 1603237 See CHP407F for violation. Defect was not recorded on the current DVIR.

Safety Fitness Rating Information:

Total Miles Operated	1,000,001
Recordable Accidents	0

OOS Vehicle (CR):	0
Number of Vehicle Inspected (CR):	0
OOS Vehicle (MCMIS):	0
Number of Vehicles Inspected (MCMIS):	0

Your proposed safety rating is :

This Review is not Rated.





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal  
U.S. DOT #: 2808913 State #: 49302

5 of 26

Review Date:  
03/10/2023

### Part B Requirements and/or Recommendations

1. Questions related to this inspection may be directed to the Border Division Motor Carrier Safety Unit Supervisor at (858) 944-6345
2. Ensure drivers prepare and submit signed daily vehicle inspection reports that accurately report defects present on each vehicle operated. A negative report shall indicate that no such conditions are present. Retain these records for 3 months.





RIVERSIDE COUNTY SCHOOLS (COACHELLA VALLEY UNIFIED dba) - Terminal  
 U.S. DOT #: 2808913 State #: 49302

6 of 26

Review Date:  
03/10/2023

**Part C**

Reason for Review: Other CSAT  
 Planned Action: Compliance Monitoring

**Parts Reviewed Certification:**

325 382 383 387 390 391 392 393 395 396 397 398 399 171 172 173 177 178 180

Prior Reviews      Prior Prosecutions      Reason not Rated: Special Study      Study Code: CA  
 3/4/2022  
 3/4/2022  
 4/15/2021

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle?      Yes - Intrastate  
 Does carrier transport placardable quantities of hazardous materials?  
 Unsat/Unfit rule:      Not Applicable

Corporate Contact: EDWARD TORRES      Special Study Information:  
 Corporate Contact Title: SUPERVISOR

**Remarks:**

Terminal Name: Coachella Valley Unified School District      CA # - 49302  
 Terminal Address: 87225 Church St Thermal CA      FCN # - 17323

**RATING INFORMATION:**

In accordance with 13 CCR 1233, this terminal has been rated satisfactory.

There were no on-highway inspections to fulfill the required vehicle inspection sample 20 school buses.

For specific violations see part B.

**REFERENCES**

The full text of the California Vehicle Code (CVC) is available online at [leginfo.ca.gov/calaw](http://leginfo.ca.gov/calaw), and the full text of Title 13, California Code of Regulations, (13CCR), is available online at [ccr.oal.ca.gov](http://ccr.oal.ca.gov). Links to these two sites can be found at [chp.ca.gov](http://chp.ca.gov).

Upload Authorized:	Yes	No
Authorized by:		Date:
Uploaded:	Yes	No
Verified by:		Failure Code:
		Date:



DRIVER/VEHICLE EXAMINATION REPORT



California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002002  
Inspection Date: 03/07/2023  
Start: 7:15 AM PS End: 7:45 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

Milepost:

Origin: N/A

Destination: N/A

Shipper: N/A

Bill of Lading: N/A

Cargo: N/A

State:

State:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2002	CA	1238998	07	1HVBADR62A940105	37000		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 357635; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 10/26/2022

Report Prepared By:  
S. Spaunhurst

ID/Badge #:  
A14627

Copy Received By:

X

X



02808913 CA CANBAB002002



**California Highway Patrol**  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

**Report Number:** CANBAB002004  
**Inspection Date:** 03/08/2023  
**Start:** 5:15 AM PS **End:** 5:45 AM PS  
**Inspection Level:** V - Terminal  
**HM Inspection Type:** None

**Carrier:** COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

**DBA:** RIVERSIDE COUNTY SCHOOLS

87050 57TH AVE  
 THERMAL, CA, 92274

**USDOT:** 2808913

**MC/MX#:**

**State#:** 49302

**Location:** THERMAL

**Highway:** CHURCH ST

**County:** RIVERSIDE

**Email:** APOLONIO.DELTORO@CVUSD.US

**Driver:**

**License#:**

**Date of Birth:**

**CoDriver:**

**License#:**

**Date of Birth:**

**State:**

**State:**

**Milepost:**

**Shipper:** N/A

**Origin:**

**Destination:**

**Bill of Lading:** N/A

**Cargo:**

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2003	CA	1265589	23	4DRBJADR13A955646	36200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

**VIOLATIONS**

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(a) T-13 CCR/001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Right side emergency door seat does not stay in the upright position

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 467169; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

**Notes:** LAST CERT 07/20/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

**Report Prepared By:** S. Spaunhurst  
**ID/Badge #:** A14627

**Copy Received By:**

X

X







California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002005  
Inspection Date: 03/07/2023  
Start: 6:45 AM PS End: 7:15 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913  
MC/MX#:

Phone#: (760)399-5127  
Fax#: (760)399-8417

Driver:  
License#:  
Date of Birth:  
CoDriver:  
License#:  
Date of Birth:  
State:  
State:

State#: 49302  
Location: THERMAL  
Highway: CHURCH ST  
County: RIVERSIDE  
Email: APOLONIO.DELTORO@CVUSD.US

Milepost:  
Origin: N/A  
Destination: N/A  
Shipper: N/A  
Bill of Lading: N/A  
Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2004	CA	1265502	33	4HDRBJADR44A95873	36200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20*	L-30

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 446514; File Code Number: 17323; Fuel Type: CNG; Passenger Capacity: 78; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

**Notes:** LAST CERT 08/24/2022

Report Prepared By: S. Spaunhurst  
ID/Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB002005

DRIVER/VEHICLE EXAMINATION REPORT



California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002006  
Inspection Date: 03/07/2023  
Start: 5:45 AM PS End: 6:15 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2004	CA	1265602	35	4DRBJADR84A958738	36220		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20*	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 483790; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 08/24/2022

Report Prepared By: ID/Badge #:  
S. Spaunhurst A14627

Copy Received By:

X

X



02808913 CA CANBAB002006



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002007
Inspection Date: 03/07/2023
Start: 6:15 AM PS End: 6:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL
DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS
87050 57TH AVE
THERMAL, CA, 92274

USDOT: 2808913
MC/MX#: 49302

Phone#: (760)399-5127
Fax#: (760)399-8417

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:

State:
State:

Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE
Email: APOLONIO.DELTORO@CVUSD.US

Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 140396; File Code Number: 17323; Fuel Type: CNG; Passenger Capacity: 76; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 11/02/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
ID/Badge #: A14627

Copy Received By:

X

X





California Highway Patrol  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002008  
 Inspection Date: 03/07/2023  
 Start: 7:45 AM PS End: 8:15 AM PS  
 Inspection Level: V - Terminal  
 HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
 87050 57TH AVE  
 THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1265690	57	1T7YU4A2281289129	36200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	1 1/2	1 3/4
Left	1 1/2	1 3/4
Chamber	C-30	C-30

**VIOLATIONS**

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Bus not swept
1268 T-13 CCR	S	1	N		N	N	Bus and FLV, emergency exit is inadequate--392.2--Specify:: Rear and side emergency exit windows do not have a light and warning buzzer in drivers compartment

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

**State Information:**

Odometer: 128432; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 05/25/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spauhurst  
 ID/Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB002008



California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002012  
Inspection Date: 03/08/2023  
Start: 7:45 AM PS End: 8:15 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS

87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

Milepost:

Origin: N/A

Destination: N/A

Shipper: N/A

Bill of Lading: N/A

Cargo: N/A

State:

State:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2008	CA	1265685	59	1T7YU4A2081289131	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	C-30	C-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 118185; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 06/22/2022

Chips in windshield both sides

Report Prepared By: ID/Badge #  
S. Spaunhurst A14627

Copy Received By:

X

X





**California Highway Patrol**  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

**Report Number:** CANBAB002009  
**Inspection Date:** 03/08/2023  
**Start:** 5:45 AM PS **End:** 6:15 AM PS  
**Inspection Level:** V - Terminal  
**HM Inspection Type:** None

**Carrier:** COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

**DBA:** RIVERSIDE COUNTY SCHOOLS

87050 57TH AVE  
 THERMAL, CA, 92274

**USDOT:** 2808913

**MC/MX#:**

**State#:** 49302

**Location:** THERMAL

**Highway:** CHURCH ST

**County:** RIVERSIDE

**Email:** APOLONIO.DELTORO@CVUSD.US

**Driver:**

**License#:**

**Date of Birth:**

**CoDriver:**

**License#:**

**Date of Birth:**

**State:**

**State:**

**Milepost:**

**Shipper:** N/A

**Origin:** N/A

**Destination:** N/A

**Bill of Lading:** N/A

**Cargo:** N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265527	105	1HVBADR6YA930196	37000		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	L-20	L-30

**VIOLATIONS**

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.2	F	1	N		N	N	Violation of Local Laws - Explain:: 13CCR 1294(a) All school buses shall be equipped with a child safety alert system meeting the requirements of this section
1232(A) CCR /001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Need seat repairs
1232(a) T-13 CCR/001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Right side emergency door seat bottom is missing
1232(A) CCR /001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Inspection certificate holder--392.2 certicatcan needs to be easily inserted and removed and is clearly legible

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 418826; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 1

**Notes:** LAST CERT 10/26/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

**Report Prepared By:** S. Spaunhurst  
**ID/Badge #:** A14627

**Copy Received By:**

X

X





California Highway Patrol  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002010  
 Inspection Date: 03/08/2023  
 Start: 6:15 AM PS End: 6:45 AM PS  
 Inspection Level: V - Terminal  
 HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
 87050 57TH AVE  
 THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWWR	CVSA Existing	CVSA #
1	SB	INTL	2000	CA	1265504	106	1HVBADR8YA930197	37000		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	1 1/4	1 3/4
Left	1 1/4	1 3/4
Chamber	L-20	L-30

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 432045; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 1

**Notes:** LAST CERT 07/20/2022

Report Prepared By: ID/Badge #:  
 S. Spaunhurst A14627

Copy Received By:

X

X



02808913 CA CANBAB002010



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002013
Inspection Date: 03/07/2023
Start: 8:15 AM PS End: 8:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL
DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS
87050 57TH AVE
THERMAL, CA, 92274

USDOT: 2808913
MC/MX#: 49302

Phone#: (760)399-5127
Fax#: (760)399-8417

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:

State:
State:

Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE
Email: APOLONIO.DELTORO@CVUSD.US

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 126977; File Code Number: 17323; Fuel Type: CNG; Passenger Capacity: 65; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 1

Notes: LAST CERT 12/07/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
ID/Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB002013





California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002016  
Inspection Date: 03/08/2023  
Start: 8:45 AM PS End: 9:15 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913  
MC/MX#:

Phone#: (760)399-5127  
Fax#: (760)399-8417

Driver:  
License#:  
Date of Birth:  
CoDriver:  
License#:  
Date of Birth:

State:  
  
State:

State#: 49302  
Location: THERMAL  
Highway: CHURCH ST  
County: RIVERSIDE  
Email: APOLONIO.DELTORO@CVUSD.US

Milepost:  
Origin: N/A  
Destination: N/A  
Shipper: N/A

Bill of Lading: N/A  
Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWR	CVSA Existing	CVSA #
1	SB	CHEV	2022	CA	1632675	513	1HA6GUB70MN004996	14200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 17692; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 31; WC Passenger Capacity: 1; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

**Notes:** LAST CERT 04/21/2022

Report Prepared By: S. Spauhurst  
ID/Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB002016



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002017
Inspection Date: 03/07/2023
Start: 10:45 AM PS End: 11:15 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS
87050 57TH AVE
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127
Fax#: (760)399-8417

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:

State:
State:

Milepost: Shipper: N/A
Origin:
Destination:

Bill of Lading: N/A
Cargo:

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber and values for axles 1 and 2

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 26989; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 31; WC Passenger Capacity: 1; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 04/21/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
ID/Badge #: A14627

Copy Received By:

X

X





California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002015  
Inspection Date: 03/08/2023  
Start: 10:45 AM PS End: 11:15 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

Milepost:

Origin: N/A

Destination: N/A

Shipper: N/A

Bill of Lading: N/A

Cargo: N/A

State:

State:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2022	CA	1632680	519	1HA6GUB78MN005913	14200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 25552; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 31; WC Passenger Capacity: 1; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 1

Notes: LAST CERT 05/25/2022

Report Prepared By: S. Spaunhurst  
ID/Badge #: A14627

Copy Received By:

X

X





**California Highway Patrol**  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

**Report Number:** CANBAB002018  
**Inspection Date:** 03/08/2023  
**Start:** 9:15 AM PS **End:** 10:45 AM PS  
**Inspection Level:** V - Terminal  
**HM Inspection Type:** None

**Carrier:** COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

**DBA:** RIVERSIDE COUNTY SCHOOLS

87050 57TH AVE  
 THERMAL, CA, 92274

**USDOT:** 2808913

**MC/MX#:**

**State#:** 49302

**Location:** THERMAL

**Highway:** CHURCH ST

**County:** RIVERSIDE

**Email:** APOLONIO.DELTORO@CVUSD.US

**Driver:**

**License#:**

**Date of Birth:**

**CoDriver:**

**License#:**

**Date of Birth:**

**Milepost:**

**Origin:** N/A

**Destination:** N/A

**Shipper:** N/A

**Bill of Lading:** N/A

**Cargo:** N/A

**State:**

**State:**

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	CHEV	2022	CA	1632681	521	1HA6GUB7P4MN00498	14200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 14710; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 1; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

**Notes:** LAST CERT 05/19/2022

**Report Prepared By:** S. Spaunhurst  
**ID/Badge #:** A14627

**Copy Received By:**

X

X



02808913 CA CANBAB002018



California Highway Patrol  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002019  
 Inspection Date: 03/07/2023  
 Start: 9:15 AM PS End: 10:45 AM PS  
 Inspection Level: V - Terminal  
 HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
 87050 57TH AVE  
 THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	FORD	2021	CA	1626056	531	1FDFE4FN2MDC10616	14500		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

**VIOLATIONS**

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(a) T-13 CCR/001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Loose object on dash and loose broom and mop at rear of bus

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

**State Information:**

Odometer: 38169; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 23; WC Passenger Capacity: 6; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 12/07/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: ID/Badge #:  
 S. Spaunhurst A14627

Copy Received By:

X

X





California Highway Patrol  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002020  
 Inspection Date: 03/07/2023  
 Start: 8:45 AM PS End: 9:15 AM PS  
 Inspection Level: V - Terminal  
 HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
 87050 57TH AVE  
 THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	FORD	2021	CA	1626057	532	1DFDE4FNXMDC14316	14500		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Odometer: 39872; File Code Number: 17323; Fuel Type: GAS; Passenger Capacity: 23; WC Passenger Capacity: 6; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

**Notes:** LAST CERT 11/02/2022

Report Prepared By: ID/Badge #:  
 S. Spaunhurst A14627

Copy Received By:

X

X



02808913 CA CANBAB002020



California Highway Patrol  
 9330 Farnham Street  
 San Diego, CA 92123  
 Phone: (858) 944-6349  
 Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002003  
 Inspection Date: 03/08/2023  
 Start: 6:45 AM PS End: 7:15 AM PS  
 Inspection Level: V - Terminal  
 HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS

87050 57TH AVE  
 THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL

Highway: CHURCH ST

County: RIVERSIDE

Email: APOLONIO.DELTORO@CVUSD.US

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2021	CA	1603238	604	1BABNB7A3MF373230	36200		

**BRAKE ADJUSTMENTS**

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	DISC	DISC

**VIOLATIONS**

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(a) T-13 CCR/001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Left side emergency exit window difficult to open

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

**State Information:**

Odometer: 38004; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 84; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 06/22/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: ID/Badge #:  
 S. Spaunhurst A14627

Copy Received By:

X

X





California Highway Patrol  
9330 Farnham Street  
San Diego, CA 92123  
Phone: (858) 944-6349  
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002021  
Inspection Date: 03/07/2023  
Start: 5:15 AM PS End: 5:45 AM PS  
Inspection Level: V - Terminal  
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS  
87050 57TH AVE  
THERMAL, CA, 92274

USDOT: 2808913

MC/MX#:

State#: 49302

Location: THERMAL  
Highway: CHURCH ST  
County: RIVERSIDE  
Email: APOLONIO.DELTORO@CVUSD.US

Phone#: (760)399-5127

Fax#: (760)399-8417

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost: Shipper: N/A

Origin:

Destination:

Bill of Lading: N/A

Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2020	CA	1597946	608	1BABNB7A0MF373234	36200		

BRAKE ADJUSTMENTS: No brake measurements recorded

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1232(A) CCR /001	S	1	N		N	N	Motor carrier fail to ensure general maintenance of vehicle--396.3A1--Specify:: Object on dash

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 50598; File Code Number: 17323; Fuel Type: CNG; Passenger Capacity: 81; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 07/20/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: ID/Badge #:  
S. Spaunhurst A14627

Copy Received By:

X

X







California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002011
Inspection Date: 03/08/2023
Start: 7:15 AM PS End: 7:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL
DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS
87050 57TH AVE
THERMAL, CA, 92274

USDOT: 2808913
MC/MX#: State#: 49302

Phone#: (760)399-5127
Fax#: (760)399-8417

Driver: License#: State:
Date of Birth:
CoDriver: License#: State:
Date of Birth:

Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Milepost: Shipper: N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

Email: APOLONIO.DELTORO@CVUSD.US

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber and values for axles 1 and 2

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 52384; File Code Number: 17323; Fuel Type: D; Passenger Capacity: 24; WC Passenger Capacity: 7; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 07/20/2022

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
ID/Badge #: A14627

Copy Received By:

X

X



02808913 CA CANBAB002011

DRIVER/VEHICLE EXAMINATION REPORT



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CANBAB002014
Inspection Date: 03/08/2023
Start: 8:15 AM PS End: 8:45 AM PS
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: COACHELLA VALLEY UNIFIED SCHOOL
DISTRICT

DBA: RIVERSIDE COUNTY SCHOOLS
87050 57TH AVE
THERMAL, CA, 92274

USDOT: 2808913
MC/MX#: 49302

Phone#: (760)399-5127
Fax#: (760)399-8417

Driver:
License#:
Date of Birth:
State:

CoDriver:
License#:
Date of Birth:
State:

Location: THERMAL
Highway: CHURCH ST
County: RIVERSIDE

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

Email: APOLONIO.DELTORO@CVUSD.US

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #. Row 1: 1, SB, BLUB, 2020, CA, 1603173, 610, 1BABNB7A4MV373236, 36200

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber. Rows for Axle # 1 and 2, Right and Left, Chamber DISC

VIOLATIONS

Table with columns: Section, Type, Unit, OOS, Citation #, Verify, Crash, Violations Discovered. Rows for 1232(a) T-13 CCR/001 and 1232(a) T-13 CCR/001

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 55209; File Code Number: 17323; Fuel Type: CNG; Passenger Capacity: 81; Bus Type: 1; Beat/Sub Area: B15; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 13

Notes: LAST CERT 05/25/2022

Crack in windshield passenger side

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Spaunhurst
ID/Badge #: A14627

Copy Received By:

X

X



STATE OF CALIFORNIA  
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

3/8/2023 12:13:21 PM



**Basic Terminal Information for Term#: 17323**  
**COACHELLA VALLEY UNIFIED SCHOOL DISTRICT, CA# 49302**

<p><b>Location</b> 87225 CHURCH ST THERMAL, CA, US92274 (760) 399-5127 CHP Area: 630 County Code: 33 Sub Area: B15</p>	<p><b>Mailing Address</b> P O BOX 847 THERMAL, CA US 92274-0847</p>
--	---

**Fleet Information**  
Trucks: 1 Vehicles: 98 Bus 1: 97 Drivers: 84  
Types Owned: N/A  
Types of Operation: SBUS


**Terminal Emergency Contacts**

ANTONIO MURILLO	Day: (760) 399-5127	[REDACTED]
APOLONIO DEL TORE (POLO)	Day: (760) 399-5127	

<b>Status</b>	<b>California Mileage</b>	<b>IMS License</b>
ACTIVE as of 09/06/1988	Year Mileage	
Last 343 Update: 03/08/2022	2021 1000001	
Driver Records: Yes	2020 100001	
Vehicle Records: Yes		

**Inspection History**

Inspection Date	Maint.	Driver	Equip	Hazmat	Term	CHP345 Issued	BIT-Inspection Conducted	Inspection Type	Suspe Dat
3/4/2022	S	S	S	N/A	S	NO	Not Applicable	SBUS	3
4/15/2021	S	S	S	N/A	S	NO	Not Applicable	SBUS	4/1
4/17/2020	S	N/A	S	N/A	S	NO	Not Applicable	SBUS	4/1
10/30/2019	C	N/A	C	N/A	C	NO	Not Applicable	SBUS	4/2
6/28/2019	U	S	U	N/A	U	YES	Not Applicable	SBUS	10/2
7/12/2018	S	S	S	N/A	S	NO	Not Applicable	SBUS	7/1
7/27/2017	S	S	S	N/A	S	NO	Not Applicable	SBUS	7/2
2/3/2017	C	N/A	C	N/A	C	NO	Not Applicable	SBUS	8
10/13/2016	U	N/A	U	N/A	U	YES	Not Applicable	SBUS	2/1
6/16/2016	U	N/A	U	N/A	U	YES	Not Applicable	SBUS	10/1
6/13/2016	U	N/A	U	N/A	U	NO	Not Applicable	SBUS	10/1
3/4/2016	U	S	U	N/A	U	NO	Not Applicable	SBUS	7
2/27/2015	S	S	S	N/A	S	NO	Not Applicable	SBUS	2
3/12/2014	S	S	S	N/A	S	NO	Not Applicable	SBI IS	3



Choose Subsystem Go

Exit MCMIS

### View Company Record



Identification	Operation Classification	Cargo Classification	Hazardous Materials	Equipment	Drivers	Show All Data
----------------	--------------------------	----------------------	---------------------	-----------	---------	---------------

USDOT Number:	2808913	Application Tracking Number:	
Company Type:	CARRIER		

Identification			
Status:	ACTIVE	MC/MX Number:	
Legal Name:	COACHELLA VALLEY UNIFIED SCHOOL DISTRICT		
DBA Name (Doing Business As):	RIVERSIDE COUNTY SCHOOLS		

Physical Address			
Street:	87050 57TH AVE		
City:	THERMAL		
State / Country:	CALIFORNIA	ZIP/Postal Code:	92274
Colonia (Mexico Only):		County:	RIVERSIDE
Phone#:	7603995127	Cell Phone#:	7608357149
		Fax#:	7603998417

Mailing Address			
Street (PO Box):	PO BOX 847		
City:	THERMAL		
State / Country:	CALIFORNIA	ZIP/Postal Code:	92274
Colonia (Mexico Only):		Mailing County:	RIVERSIDE

Other			
Dun & Bradstreet No.:		Canada NSC:	
State Director Code:	06	Service Center:	WESTERN
Internet E-Mail Address:	APOLONIO.DELTORO@CVUSD.US		
MCS-150 Date (MM/DD/YYYY):	03/26/2021		
MX Type:		RFC Number:	
New Entrant Status:	EXITED FROM NEW ENTRANT PROGRAM WITH SA		
New Entrant Entry Date:	04/10/2017	New Entrant Exit Date:	10/11/2018
Name of Authorized Person:	APOLONIO DEL TORO	Title of Authorized Person:	DIRECTOR OF TRANSPORTATION
Do not put in NE Program (Y/N):	<input checked="" type="radio"/> YES <input type="radio"/> NO		
1. Officer Name:	APOLONIO DEL TORO		
1. Officer Title:	DIRECTOR OF TRANSPORTATION		
2. Officer Name:			
2. Officer Title:			

Carrier/Shipper	