

**SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE**

CHP 343 (Rev 12-17) OPI 062

NEW TERMINAL INFORMATION <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CA NUMBER 14019	FILE CODE NUMBER 14829	COUNTY CODE 33	BED
TERMINAL TYPE <input type="checkbox"/> Truck <input checked="" type="checkbox"/> Bus <input type="checkbox"/> Mod Limo	CODE S	OTHER PROGRAM(S) T	LOCATION CODE 630	SUBAREA B17

CARRIER LEGAL NAME First Student Inc	TERMINAL NAME (IF DIFFERENT)	TELEPHONE NUMBER (WAREA CODE) (760) 320-8822
---	------------------------------	---

TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE)
5006 Calle San Raphael Palm Springs 92264

MAILING ADDRESS (NUMBER, STREET, CITY, STATE, ZIP CODE) (IF DIFFERENT FROM ABOVE) Same
INSPECTION LOCATION (NUMBER, STREET, CITY OR COUNTY) 5006 Calle San Raphael Palm Springs

LICENSE, FLEET AND TERMINAL INFORMATION

HMLIC NO	HWT REG NO	IMS LIC NO	TRUCKS AND TYPES	TRAILERS AND TYPES	PASS VEH BY TYPE I 99 II	Mod Limo <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	DRIVERS 67	BIT FLEET SIZE Powered
EXP DATE	EXP DATE	EXP DATE	REG CT	HW VEH	HW CONT	PPB / CSAT <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A		Towed
TERMINALS IDENTIFIED IN SECTION 34515(b) CVC <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			FILE CODE NUMBERS OF TERMINALS INCLUDED IN INSPECTION AS A RESULT OF SECTION 34515(b) CVC					

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) Domingo Velazco	DAY TELEPHONE NO (WAREA CODE) (760) 320-8822	NIGHT TELEPHONE NO (WAREA CODE) (760) 396-6452
EMERGENCY CONTACT (NAME) Matthew LaFond	DAY TELEPHONE NO (WAREA CODE) (760) 320-8822	NIGHT TELEPHONE NO (WAREA CODE)

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL LAST YEAR [2021]

A UNDER 15,000	B 15,001 - 50,000	C 50,001 - 100,000	D 100,001 - 500,000	E 500,001 - 1,000,000	F 1,000,001 - 2,000,000	G 2,000,001 - 5,000,000	H 5,000,001 - 10,000,000	I MORE THAN 10,000,000
----------------	-------------------	--------------------	---------------------	-----------------------	-------------------------	-------------------------	--------------------------	------------------------

OPERATING AUTHORITIES OR PERMITS

PUC <input type="checkbox"/> T <input type="checkbox"/> TCP <input type="checkbox"/> PSC	MOTOR CARRIER OF PROPERTY PERMIT ACTIVE <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	IMS FITNESS EVALUATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
USDOT 354406	MC 191534 MX	REASON FOR INSPECTION School Bus Terminal Inspection

INSPECTION FINDINGS INSPECTION RATINGS: S = Satisfactory U = Unsatisfactory C = Conditional UR = Unrated N/A = Not Applicable

REQUIREMENTS	VIOL	MAINTENANCE PROGRAM	DRIVER RECORDS	REG EQUIPMENT	HAZARDOUS MATERIALS	TERMINAL
MAINTENANCE PROGRAM		1 S 2 S 3 S 4 S	1 S 2 S 3 S 4 S	1 S 2 S 3 S 4 S	1 N/A 2 N/A 3 N/A 4 N/A	1 S 2 S 3 S 4 S
DRIVER RECORDS		No 20 Time 4.0	No 17 Time 2.0	No 20 Time 16.0	TIME	TOTAL TIME 22.0
DRIVER HOURS		HAZARDOUS MATERIALS <input checked="" type="checkbox"/> No H/M Transported <input type="checkbox"/> No H/M violations noted	CONTAINERS/TANKS No. Time	VEHICLES PLACED OUT-OF-SERVICE Vehicles Units		
BRAKES		REMARKS SCHOOL BUS TERMINAL INSPECTION See attached pages (Part B and Part C) for inspection findings Buses inspected were for terminal representative sample only				
LAMPS & SIGNALS						
CONNECTING DEVICES						
STEERING & SUSPENSION						
TIRES & WHEELS						
EQUIPMENT REQUIREMENTS	3					
CONTAINERS & TANKS						
HAZARDOUS MATERIALS						

INSPECTION TYPE <input checked="" type="checkbox"/> I <input type="checkbox"/> R	NON-BIT <input checked="" type="checkbox"/>	CPSS <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CHP 345 <input type="checkbox"/>	CHP 100D COL <input type="checkbox"/>	INSPECTION DATE(S) 12/13-15/22	TIME IN 0730	TIME OUT 1500
INSPECTED BY (NAME(S)) S. Larkins				ID NUMBER(S) A11414	SUSPENSE DATE <input type="checkbox"/> Auto <input checked="" type="checkbox"/> None		

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through 26), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at 858-944-6345 within 5 business days of the rating.

CURRENT TERMINAL RATING SATISFACTORY	CARRIER REPRESENTATIVE'S SIGNATURE <i>Michael Robinson</i>	DATE 12/15/2022
CARRIER REPRESENTATIVE'S PRINTED NAME Michael Robinson	TITLE Terminal Manager	DRIVER LICENSE NUMBER STATE

California Highway Patrol

PG 2 OF 26



US DOT #
354406

Legal: FIRST STUDENT INC
Operating (DBA):

MC/MX #: 191534 State #: 14019

Review Type: Non-ratable Review - Special Study

Scope: Terminal

Location of Review/Audit: Company facility in the U. S.

Territory:

Operation Types Interstate Intrastate

Carrier: Non-HM N/A
Shipper: N/A N/A
Cargo Tank: N/A

Business: Corporation
Gross Revenue: \$0.00 for year ending:

Company Physical Address:

600 VINE ST SUITE 1400
CINCINNATI, OH 45202

Contact Name:

Phone numbers: (1) 513-241-2200 (2) Fax
E-Mail Address: Domingo.Velazco@firstgroup.com

Company Mailing Address:

600 VINE ST SUITE 1400
CINCINNATI, OH 45202

Carrier Classification

Authorized for Hire

Cargo Classification

Passengers

Equipment

	Owned	Term	Leased	Trip	Leased	Owned	Term	Leased	Trip	Leased
School Bus, 16+	99		0		0					

Power units used in the U.S.: 99

Percentage of time used in the U.S.: 100

Does carrier transport placardable quantities of HM? No

Is an HM Permit required? N/A

Driver Information

	Inter	Intra	Average trip leased drivers/month:
< 100 Miles:	0	67	Total Drivers: 67
>= 100 Miles:	0	0	CDL Drivers: 67





FIRST STUDENT INC - Terminal

U.S. DOT #: 354406

PG 3 OF 26

State #: 14019

Review Date:

12/15/2022

Part A

QUESTIONS regarding this report may be addressed to the Border Division
Motor Carrier Safety Unit

9330 Farnham Street
San Diego Ca. 92123
(858) 944-6345

This TERMINAL REVIEW deals only with safety compliance at this terminal.

Person(s) Interviewed

Name: Michael Robinson

Title: Terminal Manager

Name:

Title:





FIRST STUDENT INC - Terminal
U.S. DOT #: 354406

PG 4 OF 26
State #: 14019

Review Date:
12/15/2022

Part B Violations

Safety Fitness Rating Information:

Total Miles Operated 1,164,228
Recordable Accidents 0

OOS Vehicle (CR): 0
Number of Vehicle Inspected (CR): 20
OOS Vehicle (MCMIS): 0
Number of Vehicles Inspected (MCMIS): 0

Your proposed safety rating is :

This Review is not Rated.





FIRST STUDENT INC - Terminal

U.S. DOT #: 354406

PG 5 OF 26

State #: 14019

Review Date:

12/15/2022

Part B Requirements and/or Recommendations

1. 13CCR 1233.5 Carrier is required to notify the Department, in writing, of any change of address or cessation of regulated activity at any of the carrier's terminal. Such notification shall be made within 15 days of the change and shall be forwarded to:

CALIFORNIA HIGHWAY PATROL
COMMERCIAL RECORDS UNIT
P.O. BOX 942898
SACRAMENTO, CA 94298-0001

2. Forms and publications are available at the CHP internet website at: <https://www.chp.ca.gov/home/forms>





FIRST STUDENT INC - Terminal
 U.S. DOT #: 354406

PG 6 OF 26

State #: 14019

Review Date:
 12/15/2022

Part C

Reason for Review: Other School Bus Terminal
Planned Action: Compliance Monitoring

Parts Reviewed Certification:

325 382 383 387 390 391 392 393 395 396 397 398 399 171 172 173 177 178 180

Prior Reviews **Prior Prosecutions** **Reason not Rated: Special Study** **Study Code: CA**
 12/7/2021
 12/8/2020
 12/19/2019

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle? No

Does carrier transport placardable quantities of hazardous materials?
 Unsat/Unfit rule: Not Applicable

Corporate Contact: Michael Robinson **Special Study Information:**
Corporate Contact Title: Terminal Manager

Remarks:

TERMINAL NAME: First Student Inc. CA # - 14019
 Terminal Address: 5006 Calle San Raphael. Palm Springs Ca. 92264 FCN - 14829

RATING INFORMATION:

In accordance with 13 CCR 1233, this terminal has been rated Satisfactory at this time.

No on highway inspections available at the time of inspection

MAINTENANCE PROGRAM VIOLATIONS:

No violations noted

DRIVER RECORDS VIOLATIONS:

No violations noted

HOURS OF SERVICE VIOLATIONS:

No violations noted

Upload Authorized:	Yes	No
Authorized by:		Date:
Uploaded:	Yes	No
Verified by:		Failure Code:
		Date:





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001280
Inspection Date: 12/13/2022
Start: 8:00 AM PT End: 9:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:

State:

State:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost:
Origin:
Destination:

Shipper: N/A

Bill of Lading: N/A
Cargo:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	35683X1	324365	1BABNBAA5GF324365	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	2
Left	1 1/2	1 3/4
Chamber	L-24	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 91630; File Code Number: 14829; Fuel Type: CNG; Passenger Capacity: 78; WC Passenger Capacity: 0; Bus Type: 1; School Bus Cert: 8/4/2022 12:00:00 AM; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 8-4-22 / 86534
LAST 45/3000: 11-23-22 / 91260
CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001281
Inspection Date: 12/13/2022
Start: 9:00 AM PT End: 10:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Milepost:

Shipper: N/A

Highway:

Origin: N/A

Bill of Lading: N/A

County: RIVERSIDE

Destination: N/A

Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX938	324352	1BABNBAA7GF324352	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 3/4	1 3/4
Left	1 1/2	1 3/4
Chamber	L-24	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 94229; File Code Number: 14829; Fuel Type: CNG; Passenger Capacity: 78; WC Passenger Capacity: 0; Bus Type: 1; School Bus Cert: 3/8/2022 12:00:00 AM; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 3-8-22 / 87693

LAST 45/3000: 11-17-22 / 93900

CSAS OEPRATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001282
Inspection Date: 12/13/2022
Start: 10:00 AM PT End: 10:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Milepost:

Shipper: N/A

Highway:

Origin: N/A

Bill of Lading: N/A

County: RIVERSIDE

Destination: N/A

Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX771	324383	1BAKCCBH8GF324383	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 76462; File Code Number: 14829; Fuel Type: LPG; Passenger Capacity: 26; WC Passenger Capacity: 15; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 10-11-22 / 76434

LAST 45/3000: 12-13-22 / 76462

CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001283
Inspection Date: 12/13/2022
Start: 10:30 AM PT End: 11:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX915	324343	1BABNBAA6GF324343	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 3/4
Left	1 1/2	1 3/4
Chamber	L-24	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 86207; File Code Number: 14829; Fuel Type: CNG; Passenger Capacity: 78; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 1-18-22 / 74501
LAST 45/3000: 11-29-22 / 85507
CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins
Unit #: 611
ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
 9330 Farnham Street
 San Diego, CA 92123
 Phone: (858) 944-6349
 Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001284
Inspection Date: 12/13/2022
Start: 11:30 AM PT **End:** 12:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
 600 VINE ST SUITE 1400
 CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Location: PALM SPRINGS

Milepost: **Shipper:** N/A

Highway:

Origin: N/A

Bill of Lading: N/A

County: RIVERSIDE

Destination: N/A

Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	COLL	2015	CA	7PUP729	278832	1GB6G5BG1F1278832	14200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 70090; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 24; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 12-5-22 / 65470
 LAST 45/3000: 11-8-22 / 69255
 CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins
Unit #: 611
ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001285
Inspection Date: 12/13/2022
Start: 12:00 PM PT End: 12:30 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202
USDOT: 354406 Phone#: (513)241-2200
MC/MX#: 191534 Fax#: (513)672-9581
State#: 14019
Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
Milepost: Shipper: N/A
Origin: N/A
Destination: N/A
State:
State:
Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	COLL	2015	CA	7NUN863	152328	1GB3G3BG6F1167989	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 130189; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 10-11-22 / 127942
LAST 45/3000: 12-12-22 / 130147
CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001286
Inspection Date: 12/13/2022
Start: 12:30 PM PT End: 1:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202
USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost: **Shipper:** N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX240	324371	1BAKCCBH1GF324371	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 76100; File Code Number: 14829; Fuel Type: LPG; Passenger Capacity: 26; WC Passenger Capacity: 15; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 7-12-22 / 70476
LAST 45/3000: 11-28-22 / 75284
CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X



00354406 CA CAN8T2001286



California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001287
Inspection Date: 12/13/2022
Start: 1:00 PM PT End: 1:30 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC.

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: PALM SPRINGS

Milepost: Shipper: N/A

Highway:
County: RIVERSIDE

Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	COLL	2015	CA	7PHT554	271582	1GB3G3BG3F1271582	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 59922; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 24; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 2-24-22 / 53679
LAST 45/3000: 12-12-22 / 59872
CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins
Unit #: 611
ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001288
Inspection Date: 12/13/2022
Start: 1:30 PM PT End: 2:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2014	CA	7HKU968	143014	1GB3G3BG1E1205109	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 80689; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 6-7-22 / 74262
LAST 45/3000: 12-1-22 / 80252
CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001289
Inspection Date: 12/13/2022
Start: 2:00 PM PT End: 2:30 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202
USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost: **Shipper:** N/A
Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	COLL	2015	CA	7PHS402	152334	1GB3G3BG7F1229139	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 98397; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT 1-31-22 / 87076
LAST 45/3000: 11-18-22 / 97619
CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001290
Inspection Date: 12/14/2022
Start: 8:00 AM PT End: 8:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Milepost:

Shipper: N/A

Highway:

Origin:

Bill of Lading: N/A

County: RIVERSIDE

Destination:

Cargo:

Email: cAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate, Equipment ID, VIN, GVWR, CVSA Existing, CVSA #. Row 1: 1, SB, BLUB, 2009, CA, 1302959, 12, 1BAKCCPH39F257798, 27000

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber. Rows: Axle # 1, 2; Right N/A, N/A; Left N/A, N/A; Chamber HYDR, HYDR

VIOLATIONS

Table with columns: Section, Type, Unit, QOS, Citation #, VerifyCrash, Violations Discovered. Row 1: 27000(a), S, 1, N, N, N, Vehicle is not equipped with a horn or horn is inoperative--393.81--Specify: Vehicle horn inoperative

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 236212; File Code Number: 14829; Fuel Type: D; Passenger Capacity: 32; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 6-7-22 / 231757

LAST 45/3000: 12-12-22 / 236212

CSAS OPERATING PROPERLY

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001291
Inspection Date: 12/14/2022
Start: 8:30 AM PT End: 9:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

Driver:
License#: State:

USDOT: 354406 Phone#: (513)241-2200
MC/MX#: 191534 Fax#: (513)672-9581

Date of Birth: State:
CoDriver:
License#: State:

State#: 14019
Location: PALM SPRINGS

Milepost: Shipper: N/A

Highway:
County: RIVERSIDE

Origin: N/A
Destination: N/A

Bill of Lading: N/A
Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX948	324361	1BABNBAA8GF324361	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 1/2
Left	1 1/2	1 1/2
Chamber	L-24	L-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1278(c) T-13 CCR	S	1	N		N	N	Schoolbus passenger seat cushion is not secured to frame--392.2: second and third from last seats on the right side, seat backs are torn

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 88983; File Code Number: 14829; Fuel Type: CNG; Passenger Capacity: 78; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 7-12-22 / 86324

LAST 45/3000: 11-28-22 / 88648

CSAS OPERATING PROPERLY

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001292
Inspection Date: 12/14/2022
Start: 9:30 AM PT End: 10:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Highway:

County: RIVERSIDE

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	COLL	2015	CA	7NJN178	152336	1GB3G3BG0F1233596	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 96248; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 3-8-22 / 81125

LAST 45/3000: 11-17-22 / 94884

CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001293
Inspection Date: 12/14/2022
Start: 10:00 AM PT End: 10:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202
USDOT: 354406 Phone#: (513)241-2200
MC/MX#: 191534 Fax#: (513)672-9581
State#: 14019
Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Milepost: Shipper: N/A
Origin: N/A Bill of Lading: N/A
Destination: N/A Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX242	324373	1BAKCCBH5GF324373	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS

Section	Type	Unit	QOS	Citation #	VerifyCrash	Violations Discovered
27000(a) CVC/001	S	1	N		N N	Vehicle is not equipped with a horn or horn is inoperative--393.81--Specify: Vehicle horn is inoperative

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 57952; File Code Number: 14829; Fuel Type: LPG; Passenger Capacity: 26; WC Passenger Capacity: 15; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 7-12-22 / 57855

LAST 45/3000: 12-7-22 / 57952

CSAS OPERATING PROPERLY

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001294
Inspection Date: 12/14/2022
Start: 10:30 AM PT End: 11:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

MC/MX#: 191534

State#: 14019

Location: PALM SPRINGS

Highway:

County: RIVERSIDE

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX944	324356	1BABNBAA4GF324356	36200		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 3/4	1 3/4
Left	1 3/4	1 3/4
Chamber	L-24	L-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 116514; File Code Number: 14829; Fuel Type: CNG; Passenger Capacity: 78; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 9-8-22 / 112283

LAST 45/3000: 12-7-22 / 116224

CSAS OEPRATING PROPERLY

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001295
Inspection Date: 12/14/2022
Start: 11:30 AM PT End: 12:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

MC/MX#: 191534

State#: 14019

Location: PALM SPRINGS

Highway:

County: RIVERSIDE

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

State:

State:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	COLL	2015	CA	7NJN899	152344	1GB3G3BG9F1231877	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 120296; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 7-12-22 / 112340

LAST 45/3000: 11-28-22 / 119225

CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001296
Inspection Date: 12/14/2022
Start: 12:00 PM PT End: 12:30 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

MC/MX#: 191534

State#: 14019

Location: PALM SPRINGS

Highway:

County: RIVERSIDE

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

State:

State:

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX768	324380	1BAKCCBH2GF324380	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 71709; File Code Number: 14829; Fuel Type: LPG; Passenger Capacity: 27; WC Passenger Capacity: 8; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 6-7-22 / 69616

LAST 45/3000: 11-15-22 / 70673

CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001297
Inspection Date: 12/14/2022
Start: 12:30 PM PT End: 1:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Milepost:

Shipper: N/A

Highway:

Origin: N/A

Bill of Lading: N/A

County: RIVERSIDE

Destination: N/A

Cargo: N/A

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	COLL	2015	CA	8BTZ388	278207	1GB3G3BG1F1278207	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS:No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 66522; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 24; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 6-23-22 / 62633

LAST 45/3000: 11-8-22 / 65264

CSAS OPERATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001298
Inspection Date: 12/14/2022
Start: 1:00 PM PT End: 1:30 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:
600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406
MC/MX#: 191534
State#: 14019

Phone#: (513)241-2200
Fax#: (513)672-9581

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:

State:

State:

Location: PALM SPRINGS
Highway:
County: RIVERSIDE
Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Milepost:
Origin: N/A
Destination: N/A
Shipper: N/A

Bill of Lading: N/A
Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	THMS	2014	CA	7HKU379	143043	1GB3G3BG2E1206706	12300		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 60289; File Code Number: 14829; Fuel Type: GAS; Passenger Capacity: 20; WC Passenger Capacity: 0; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 6-7-22 / 57161
LAST 45/3000: 12-12-22 / 60134
CSAS OEPRATING PROPERLY

Report Prepared By:
S. Larkins

Unit #:
611

ID/Badge #:
A11414

Copy Received By:

X

X





California Highway Patrol
9330 Farnham Street
San Diego, CA 92123
Phone: (858) 944-6349
Internationally Accredited Agency CHP407F/343A

Report Number: CAN8T2001299
Inspection Date: 12/14/2022
Start: 1:30 PM PT End: 2:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: FIRST STUDENT INC

DBA:

600 VINE ST SUITE 1400
CINCINNATI, OH, 45202

USDOT: 354406

Phone#: (513)241-2200

MC/MX#: 191534

Fax#: (513)672-9581

State#: 14019

Location: PALM SPRINGS

Highway:

County: RIVERSIDE

Email: CAROLINA.LAGUNAS@FIRSTGROUP.COM

Driver:

License#:

Date of Birth:

CoDriver:

License#:

Date of Birth:

Milepost:

Shipper: N/A

Origin: N/A

Destination: N/A

State:

State:

Bill of Lading: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	SB	BLUB	2016	CA	7NNX243	324374	1BAKCCBH7GF324374	27500		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: No data for special checks

State Information:

Odometer: 95256; File Code Number: 14829; Fuel Type: LPG; Passenger Capacity: 26; WC Passenger Capacity: 15; Bus Type: 1; Beat/Sub Area: B17; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 17

Notes: LAST CERT: 1-31-22 / 79985

LAST 45/3000: 12-*12-22 / 95134

CSAS OPERATING PROPERLY

Report Prepared By: S. Larkins

Unit #: 611

ID/Badge #: A11414

Copy Received By:

X

X



Viewing Terminal: FIRST STUDENT INC, Terminal #14829

View Carrier (#14019) (/CIRES/Navigation/UpdateCarrier?canbr=14019)

[View Terminal Report](#) View Terminal Letters

Status **Status As Of** **Last 362 Update** **Terminal Created On**
 Active 11/26/2019 8/5/2022 n/a

Principal Place of Business

Status **Terminal Name**
 Active FIRST STUDENT INC
Address
 5006 CALLE SAN RAPHAEL PALM SPRINGS, CA 92264
County Area Sub Area
 33 630 B17
Phone Email
 (760)320-8822 (mailto:)

Mailing Info

Address
 5006 CALLE SAN RAPHAEL PALM SPRINGS, CA US 92264

Mileage Summary

Year	Mileage
2019	1000001
2018	1000001
2017	1000001

Vehicle & Driver Info

Trucks Trailers Tanks Vehicles Drivers Fuel Bus (1) Bus (2) Limos Containers
 0 0 0 ~~X~~ 99 ~~X~~ 67 10 ~~X~~ 99 0 0 0
 Driver Rec. **Driver Rec.**

BIT Information

BIT Terminal? **BIT Eff. Date**

Show Full History / Hide Full History

Emergency Contact Info

Name Day Phone
 DOMINGO VELAZCO (760)322-8822
 MATTHEW LAFOND (760)320-8822

Types of Operation Vehicles Operated

H. School Bus
 G. Tour Bus

Inspections

Inspection Date	Inspection Type	Maintenance Rating	Driver Rating	Equipment Rating	Hazmat Rating	Terminal Rating	Admin Review	BIT Category	CHP 345 Issued	Suspense	Inspector	Bates #
8/4/2022	TBUS	S	S	S	X	S	n/a	Not Applicable	No	A-08/2023	A11414	

Cor (C)	Inspection Date	Inspection Type	Maintenance Rating	Driver Rating	Equipment Rating	Hazmat Rating	Terminal Rating	Admin Review	BIT Category	CHP 345 Issued	Suspense	Inspector	Bates #
	12/7/2021	SBUS	S	S	S	X	S	n/a	Not Applicable	No	A - 12/2022	A11414	
	8/10/2021	TBUS	S	S	S	X	S	n/a	Not Applicable	No	A - 08/2022	A11414	

Rating Legend: (S)atisfactory, (AR) = Administrative Review, (U)nsatisfactory, (N) = Unsatisfactory w/ no BIT fees, (C)onditional, (X) = Not Applicable.

Show Full History / Hide Full History

Licenses and Certificates

IMS License

Authorized IMS Inspectors

Certificates

Notes About Terminal

Show 5 entries

Filter:

Date	User ID	Type	Note Left	Related Key
04/04/2019	A17585	SYSTEM	User Set Terminal to Non-BIT	
04/20/2016	A12253	SYSTEM	User Set Terminal to BIT	
12/23/2015	A16302	SYSTEM	User Set Terminal to Non-BIT	

Showing 1 to 3 of 3 entries

Current BIT Payment Cycle for Term# 14829, FIRST STUDENT INC

BIT History for Term# 14829, FIRST STUDENT INC

Terminals Consolidated by Term# 14829, FIRST STUDENT INC